


Power rails

VBAT 11.1 V from SW1: load 10.606 A typical, 27.106 A peak; source 35 A cont, 70 A peak; fuse 15 A

5V 5 V from UB: load 0.1 A typical, 0.5 A peak; source 5.5 A cont, 8 A peak

Fuses: F1 15 A (everything on VBAT), F2 2 A (branch regulator_5v), F3 3 A (branch computer), F4 2 A (branch servo_bus), F5 4 A (branch arm_base_yaw_actuator), F6 2 A (branch arm_wrist_roll_actuator). Branch fuses sit inline in the lead they protect.

Lever splices (servo_bus_hub, star_ground, splice_vbat) are junctions of their nets.

Same-net label or power symbol = same conductor. X = pin not connected.

Declared, no pins: MOTOR_DRIVER_1_CTRL_GND, MOTOR_DRIVER_2_CTRL_GND

Text to Robot — generated from design.wiring

Title: **rover_arm: schematic**

30 parts, 38 nets, 82 wires, 2 rails

Size: A0	Rev: 74021tee	Sheet 1 / 1
File: schematic.svg	KiCad symbol style	Id: 1/1