

Power rails

VBAT 11.1 V from SW1: load 5.651 A typical, 16.051 A peak; source 35 A cont, 70 A peak; fuse 10 A

5V 5 V from U4: load 1 A typical, 5 A peak; source 5.5 A cont, 8 A peak

Fuses: F1 10 A (everything on VBAT), F2 2 A (branch regulator_5v), F3 2 A (branch servo_bus), F4 2 A (branch head_pan_actuator), F5 2 A (branch left_arm_shoulder_pitch_actuator), F6 2 A (branch right_arm_shoulder_pitch_actuator). Branch fuses sit inline in the lead they protect.

Lever splices (servo_bus_hub, star_ground, splice_vbat) are junctions of their nets.

Same net label or power symbol = same conductor. X = pin not connected.

Declared, no pins: MOTOR_DRIVER_1_CTRL_GND

Text to Robot		generated from design.wiring
Title: **eva: schematic**		
24 parts, 24 nets, 57 wires, 2 rails		
Size: A1	Rev: a203004c	Sheet 1 / 1
File: schematic.svg	KiCad symbol style	Id: 1/1