





Strain = 0.000401.7 Exp. Strain Rate 0.0001 Exp. Strain Rate 0.001 1.6 Exp. Strain Rate 0.01 Exp. Strain Rate 0.1 1.5 Normalized Stress 1.4 1.3 1.2 1.1 1.0 0.9 200 100 300 400 500 600 700 Temperature (K)


Strain = 0.001001.6 Exp. Strain Rate 0.0001 Exp. Strain Rate 0.001 1.5 Exp. Strain Rate 0.01 Exp. Strain Rate 0.1 Normalized Stress 1.4 1.2 1.0 0.9 100 200 300 400 500 600 700 Temperature (K)





























Strain = 0.10000Exp. Strain Rate 0.0001 1.4 Exp. Strain Rate 0.001 Exp. Strain Rate 0.01 Exp. Strain Rate 0.1 Normalized Stress 1.3 1.2 1.1 1.0 0.9 200 100 300 400 500 600 700 Temperature (K)

