MOTOR B MOTOR A

A0 GND +5V D13 D12 A1 MB MB MB C

A2 GND +5V D11 D10 A3 MA P -5V +5V MA MA MA C

MOTOR B potentiometer

MOTOR A potentiometer

MOTOR B MOTOR A

30 V

30 V

30 V

30 V

J.NANO 5V

USB HUB 5V

5 V

J.NANO USB

WIFI USB

MEGA USB

BMS USB

MEGA USB

