

* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.

Philip - Ross Construction

Reaktion - Kinetik



Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Address where inspection was carried out (site or other workplace):

Principi - Ross constructiv

North - Kings Cnapt



* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Block D 179-80-81 82	13/3/26 12:35pm	THE SCRAP PILING WAS TAMPERED BY DIFFERENT TRADES LEAVING THE SCAFF UNSAFE TO USE. TRADES ALSO LEAVING THE WALKING WAY AND LADDER ACCESS.	THE MISSING PARTS HAVE BEEN REPLACED AND RE-ADJUSTED	INSTRUCT ALL TRADES USING SCRAP SCAFFOLDING THAT IT IS ILLEGAL. THE EXCESS MATERIALS RELATED FROM THE OTHER TRADES HAVE BEEN REPORTED TO THE SITE MATERIALS BEING MANAGED	Philip Franky	


* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.

File 101 - Ross Construction

HOATAT-Kingscroft



* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.



Address where inspection was carried out (site or other workplace):

Reaktion - Kinas capot

Fluoride - Pass Construction

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Block B 174-473-972 #1	4/3/26 11:30 AM	THE SCRAP PILING WAS TAMPERED BY DIFFERENT TRADES LEAVING UNSAFE TO USE.	MISSING PARTS HAVE BEEN REPAIRED AND RE-ADJUSTED	INSTRUCT ALL TRADES USING SCRAP PILING TO KEEP IT SAFE. THE EXCESS OF MATERIAL HELD FROM THE OTHER SCRAP IS TAMPERING WITH SCRAP IS	Philip Fernandez	
		TRADES ALSO LEAVING MATERIAL BLOCKING THE WALKWAY PASSAGE SITE MANAGER	TRADES HAVE BEEN REPORTED TO THE	1 LEGAL		