

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

3/3

Mr A Schunke
7 Tiverton Avenue
Skelmersdale
Lancashire
WN8 8PA

Date: 19/02/2026
Our Ref: 00077114/PK
Your Ref: EHR96735

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mr A Schunke**

We refer to your instructions received on **16 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD PUMA ST-LINE VIGNALE MHEV	Colour: GREY	Speedo: 70552	Miles	
Reg No: MW23VWD	Registered: Apr 2023	Type: 5 Door Hatchback	Trans: Manual	
Vin No: WF02XXERK2NR25623	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2023			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Know
Steering: Not Known	Fuel: Petrol			Centre Belt Not Tested
Extras: Not Seen	C.C.: 999	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 123.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light to Moderate Accidental Damage Rear Bumper	Incident: 13/02/2026			
Vehicle Value: £14,226.00		Repair Cost: £9,449.50 inc VAT (66.42% of PAV)	Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the rear bumper, and to the boot.

ENGINEER'S COMMENTS

19/02/2026 - Possible more damage car has not been stripped
23/02/2026 - Revised costs rear panel damaged maximum repair costs are £9460
16/04/2026 - Final costs

VEHICLE HISTORY CHECK

16/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rr Bumper Wind Defl, Rear Bumper C-Member, Rear Number Plate, Outer Rear Panel, Rear Panel, Rr Lwr Bumper Cover, Rr Bump Deflect Cvr, Bootlid/Tailgate, Rear Badge, Badge Model, Badge Motor Typ, Rear Screen Bond Kit, R/R Outer Lamp, Bonding Kit, Car Care Kit, Zinc Spray, Spot Weld Drill, Parcel Shelf Clips

Repairable parts:-Repair R/Water Drip Panel, Repair Luggage Comp Cover

Repaint only parts:-Rear Bumper C-Member surface Paint, Outer Rear Panel New Part Painting, Rear Panel New Part Painting, Bootlid/Tailgate New Part Painting, Rear Bumper New Part Paint K1r, Rr Bumper Wind Defl New Part Paint K1n, L/Roof Frame Surface Paint, R/Roof Frame Surface Paint, Rear Towing Eye Cvr Surface Paint Plast., Roof Spoiler Surface Paint Plast., L/R Side Panel Surface Paint, R/R Side Panel Surface Paint, R/Water Drip Panel Surface Paint, L/R W-House Mldg Rr Surface Paint Plast., R/R W-House Mldg Rr Surface Paint Plast., Fuel Filler Flap Surface Paint Plast., Machine Polish, R/R Qtr Glass Deatil Mask, L/R Qtr Glass Deatil Mask, Roof Section Detail Mask, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Methods Research, Sundry Part, Anti-Corrosion

Remove And Refit parts:-Renew Rear Bumper (Removed), Add/Time For Renew Rear Bumper Cover, Renew Rear Panel With Reinforcement, Strip + Retrim Rear Floor, Fuel Flap, Renew Tailgate, Aerial Telescope, Corrosion Prote To 1St Panel

Parts to check:-Check Pre Clean, Check And Quality Control, Check And Road Test, Check Wqsh And Vacuum, Check Hybrid Risk Access, Check Hybrid Shutdown, Check Pre Diagnosis, Check Post Diagnosis

COST OF REPAIRS

The repairers, Rightway Paint and Body, WN35BD, have compiled an estimate in the sum of £3,638.02 plus parts at manufacturer's list prices plus £1,300.00 for paint and materials plus £178.38 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £649.32 to £2,988.70 in their final account. The labour charge is based on 41.8 hours at a rate of £71.50 per hour. We have also agreed that the cost of paint and materials will be limited to £1,863.12. The cost of the necessary replacement parts will be approximately £2,861.98, the specialist/sundry charges will be £160.78, the VAT liability on this repair will amount to some £1,574.92 giving a total repair cost of £9,449.50 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £800.30.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 28/04/2023. The corresponding Glass's Guide (model code: 366383001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £14,226.00 at 70552 Miles, trade value is £12,028.00 and mid value is £13,127.00. We place the pre-accident value of this particular vehicle at £14,226.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £9,450.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 19th February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 12 to 13 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Boot bumper damaged, crash bar effected.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors