

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr Raja Daif
14 Worcesters Avenue
Enfield
Middlesex
EN1 4NE


Date: 20/04/2026
Our Ref: 00078666/PK
Your Ref: 574629

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr Raja Daif**

We refer to your instructions received on **15 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: LEXUS NX 350H CVT	Colour: WHITE	Speedo: 22232	Miles
Reg No: ML72YNF	Registered: Jan 2023	Type: 5 Door Estate	Trans: Automatic
Vin No: JTJCKBEZ702007815	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2023		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Hybrid		
Extras: Not Seen	C.C.: 2487	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 238.	Centre Belt Not Tested	
Damage: Moderate to Heavy Collision/Impact LH Side Door	Incident: 14/04/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £28,500.00	Repair Cost: £13,894.30 inc VAT	(48.75% of PAV)	Roadworthy: No

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand side door, to the wheel, and to the door

ENGINEER'S COMMENTS

20/04/2026 - Possible more damage.

VEHICLE HISTORY CHECK

15/04/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Rear Bumper / Left Mount, Left Front Door /Seal / Door Joint, Sealing Strip / Moulding Frame, interior moulding / left R door frame, Rear Suspension Arm / Connection Rod, Rear Arm Left Suspension / Rear Bushing, Assembly / Steering Knuckle, Rear Suspension Shock Absorber, Sway Bar Left Link / Rear Tyre /, Rear Left Wheel & Valve / 1/4 Moulding, Soill Moulding / Front Bumper Kit, Hybrid Recharge / Body Filler Sound Pad, Lifting Tape / Door Foil / Tape, Contour Moulding /Moulding Mount Kit

Specialist/Sundry charges:-Paint & Materials, Specialist Costs

Parts to check:-Wheel Alignment

COST OF REPAIRS

The repairers, Speedy Autos, 24A Wadsworth Road, Perivale, UB6 7JD (Tel. 07999 990779), have compiled an estimate in the sum of £3,502.07 plus parts at manufacturer's list prices plus £2,254.97 for paint and materials plus £375.81 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £613.07 to £2,889.00 for the labour and £344.97 to £1,910.00 for paint and materials in their final account. The labour charge is based on 32.1 hours at a rate of £90.00 per hour. We have also agreed that the cost of paint and materials will be limited to £1,910.00. The cost of the necessary replacement parts will be approximately £6,403.77, the specialist/sundry charges will be £375.81, the VAT liability on this repair will amount to some £2,315.72 giving a total repair cost of £13,894.30 including VAT **subject to any undisclosed damage**. The costs agreed are subject to a parts discount of 2.50%. **We are pleased to confirm that we have achieved total gross savings in this matter of £1,346.69.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 12/01/2023. The corresponding CAP Guide retail value for vehicles of this type and age in the April 2026 guide is £28,500.00 at 22232 Miles, trade value is £25,550.00 and mid value is £27,025.00. We place the pre-accident value of this particular vehicle at £28,500.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £13,900.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 20th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 10 to 11 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Suspension damaged. We understand that the vehicle is not currently being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors