

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

5/5

Mr Stephen Wilson
5 Maberry Place
Troon
KA10 7LA

Date: 10/02/2026
Our Ref: 00076762/PK
Your Ref: 570886 \ 724981130

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mr Stephen Wilson**

We refer to your instructions received on **02 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN T-ROC STYLE TSI S-A	Colour: BLUE	Speedo: 34954	Miles
Reg No: SD72TJO	Registered: Dec 2022	Type: 5 Door Hatchback	Trans: Semi-Auto
Vin No: WVGZZA1ZPV540186	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2022		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1498	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 147.	Centre Belt Not Tested	
Damage: Light Accidental Damage Rear Bumper	Incident: 30/01/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £19,800.00		Repair Cost: £1,305.64 exc VAT	(6.59% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

ENGINEER'S COMMENTS

15/04/2026 -

VEHICLE HISTORY CHECK

02/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/r/R/Cent Bump Mould, R/R Whl-House Cover, Filler

Repairable parts:-Repair Rear Cover Bumper

Repaint only parts:-Rear Cover Bumper Repair Paint Plastic, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Pre Rep Diag Check, Post Rep Diag Check, E.P.A. Charge, Car Care, Methods Research, Sundry Part

Remove And Refit parts:-Rear Wheel (Wheels), Left And Right Number Plate Lamps, Remove And Refit Both

Outer Tail lamps, Rear Bumper Cover, Rear Lower Bumper Cover, Rear Parking Aid Sensors, R/R Wheelhouse Shell, R/R Wheelhouse Cover, R/R Lower Bumper Cover, Wash Vehicle, Long Driving Test

Parts to check:-Check And Quality Control, Check And Clean Car

COST OF REPAIRS

The repairers, Ingram Accident Repair Centre, 9 Whitfield Dr, Heathfield Industrial Estate, Ayr, KA8 9RX (Tel. 01292 290396), have compiled an estimate in the sum of £768.00 plus parts at manufacturer's list prices plus £278.69 for paint and materials plus £9.47 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £56.00 to £712.00 in their final account. The labour charge is based on 8.9 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £278.69. The cost of the necessary replacement parts will be approximately £138.60, the specialist/sundry charges will be £176.35, giving a total repair cost of £1,305.64 plus VAT **subject to any undisclosed damage** and as your Insured is eligible to recover the VAT there will be no tax liability for your good selves on this repair. **We are pleased to confirm that we have achieved total gross savings in this matter of £67.20.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 07/12/2022. The corresponding Guide retail value for vehicles of this type and age in the January 2026 guide is £19,800.00 at 34954 Miles, trade value is £17,100.00 and mid value is £18,450.00. We place the pre-accident value of this particular vehicle at £19,800.00 bearing in mind the condition described herein.

RESERVE

Although the total cost of this repair will be approximately £1,305.64 plus VAT we consider that a repair reserve of £1,325.00 would be reasonable on this occasion and your Insured being responsible for the VAT

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 10th February 2026, on your behalf subject to your Insured being responsible for the VAT.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP CAE AMIMI
Connexus Vehicle Assessors