

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

4/4

Mr L Stanley
27 Appleby Close
Birmingham
West Midlands
B14 6PA

Date: 23/02/2026
Our Ref: 00077230/PK
Your Ref: EHR97105

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mr L Stanley**

We refer to your instructions received on **19 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD KUGA ST-LINE	Colour: SILVER	Speedo: 2588	Miles
Reg No: BN75NBL	Registered: Oct 2025	Type: 5 Door Hatchback	Trans: Manual
Vin No: WF0FXXWPMFSA51253	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2025		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1496	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 147.	Centre Belt Not Tested	
Damage: Light Accidental Damage Rear Bumper	Incident: 19/02/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £27,531.00		Repair Cost: £9,240.79 inc VAT	(33.57% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper, to the boot, and to the rear panel

ENGINEER'S COMMENTS

26/03/2026 - Revised costs vehicle on site more damage found to rear tailgate.
31/03/2026 - Revised estimate poor colour match and rear panel damaged.
17/04/2026 - Final costs parts increase ADAS carried out rear panel damaged.

VEHICLE HISTORY CHECK

19/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, L/R Out Bumper Brkt, Rr Ctr Bumper Brkt, Rear Ctr Lwr Bracket, Rear Bumper Reinf, Rr Bumper Ctr Cover, Bootlid/Tailgate, Rear Badge, Badge Model, Engine Badge, Rear Screen Bond Kit, Rear Number Plate, Diamond Brite Kit, Clips X8, Clips X14, Clips X6, Clip X4

Repairable parts:-Repair Methods, Repair Rear Panel, Repair L/R Side Panel, Repair R/R W-Arch Moulding, Repair Miracle Pull

Repaint only parts:-Bootlid/Tailgate New Part Painting, Rear Bumper New Part Paint K1r, Rr Bumper Ctr Cover New Part Paint K1r, L/R Side Panel Repair Painting <50%, R/R W-Arch Moulding Repair Paint Plastic, Rear Panel Repair Painting >50%, L/Out/Upp A-Pillar Surface Paint, R/Out/Upp A-Pillar Surface Paint, L/Roof Frame Surface Paint, R/Roof Frame Surface Paint, Rear Cover Bumper Surface Paint Plast., Tailgate Handle Surface Paint Plast., R/R Side Panel Surface Paint, Fuel Filler Flap Surface Paint Plast., Detail Mask Rear Screen, 2 Tone Uplift Surface Paint, Detail Mask Both Qtr Glass, Detail Mask Front Screen, Roof Rails Detail Mask, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Lifting Tape, Bs10125 Charge, Epa Charge, Aries Charge, Car Care Kit, Adas Rear 360 Cam, Miracle Pull Pins, Lifting Tape, Sundry Part, Repair Methods, Anti-Corrosion

Remove And Refit parts:-Remove And Refit Rear Bumper, Renew Rear Bumper (Removed), Rear Bumper Reinforcement, L/Outer Rear Lamp, L/R Inner Wheelhouse Cover, Left Rear Bumper Bracket, L/R Door Sill Cover, Left Rear Wheel Arch Cover, Right Rear Wheel Arch Cover, Rear Inner Boot Trim, Fuel Flap, Calibrate Adas Attach Parts, Renew Tailgate, Renew Tailgate Additional Time, Left Rear Wheel, Right Rear Wheel, Fuel Filler Pipe, Rear Mudflaps, Ford Pre Sweep, Ford Post Sweep, Corrosion Prote 1 Panel

Parts to check:-Check Parking Help Sensor, Check Pre Clean Car, Check Wash And Vac, Check Rd Test Final Qc, Check Apply Diamond Brite

COST OF REPAIRS

The repairers, XL Motors Ltd, Bedworth Road, Coventry, Warwickshire, CV6 6LA (Tel. 02476362181), have compiled an estimate in the sum of £2,657.23 plus parts at manufacturer's list prices plus £1,265.58 for paint and materials plus £545.95 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £3,239.88. The labour charge is based on 36.7 hours at a rate of £88.28 per hour. We have also agreed that the cost of paint and materials will be limited to £1,782.94. The cost of the necessary replacement parts will be approximately £2,093.37, the specialist/sundry charges will be £584.47, the VAT liability on this repair will amount to some £1,540.13 giving a total repair cost of £9,240.79 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/10/2025. The corresponding Glass's Guide (model code: 393707001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £27,531.00 at 2588 Miles, trade value is £26,045.00 and mid value is £26,788.00. We place the pre-accident value of this particular vehicle at £27,531.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £9,250.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 23rd February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 11 to 12 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors