

Tel: 01925 403405  
Fax: 0845 077 0806  
Email: [engineer@connexus.co.uk](mailto:engineer@connexus.co.uk)

3/3

Mr Harrison Carter  
38 Wimbledon Park Road  
Southsea  
PO5 2QS



Date: 18/03/2026  
Our Ref: 00076626/GC  
Your Ref: 570634

## **Engineer Repairable Report - Supplementary Report**

Dear Sirs,

Client/Insured: **Mr Harrison Carter**

We refer to your instructions received on **26 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                      |                             |                                                                                      |                              |
|------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------|------------------------------|
| Vehicle: <b>CUPRA TERRAMAR V2 ETSI S-A</b>           | Colour: <b>GREY</b>         | Speedo: <b>2787</b>                                                                  | Miles                        |
| Reg No: <b>HT25DAO</b>                               | Registered: <b>Jul 2025</b> | Type: <b>5 Door Hatchback</b>                                                        | Trans: <b>Semi-Auto</b>      |
| Vin No: <b>VSSZZZKP7S1049297</b>                     | MOT Exp:                    | R/H/F Tyre <b>Not Kno</b>                                                            | R/H/R Tyre <b>Not Kno</b>    |
| Mods: <b>Not Seen</b>                                | Cond: <b>Good</b>           | R/H/F Belt <b>Not Tested</b>                                                         | R/H/R Belt <b>Not Tested</b> |
| Audio: <b>Not Seen</b>                               | Manf'd: <b>2025</b>         |  |                              |
| Brakes: <b>Not Known</b>                             | Tax Exp:                    |                                                                                      |                              |
| Steering: <b>Not Known</b>                           | Fuel:                       |                                                                                      |                              |
| Extras: <b>Not Seen</b>                              | C.C.: <b>1498</b>           |  |                              |
| Air Bags Deployed: <b>Not Known</b>                  | BHP: <b>147.</b>            |                                                                                      |                              |
| Damage: <b>Light Collision/Impact LH Rear Bumper</b> | Incident: <b>20/01/2026</b> | L/H/F Tyre <b>Not Kno</b>                                                            | L/H/R Tyre <b>Not Kno</b>    |
| Vehicle Value: <b>£32,974.00</b>                     |                             | Repair Cost: <b>£3,321.68 inc VAT</b>                                                | (10.07% of PAV)              |
|                                                      |                             | Roadworthy: <b>Yes</b>                                                               |                              |

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered light collision/impact damage to the left hand rear bumper.

### **ENGINEER'S COMMENTS**

16/04/2026 - Supplementary cost: Repair costs have increased due to the ADAS system requiring calibration.

### **VEHICLE HISTORY CHECK**

26/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

### **REPAIR SCHEDULE**

**New parts required:-**Rear Bumper, Rear Bumper Spoiler, L/R Bumper Guide, L/R Bumper Bracket, R/R Bumper Bracket, L/R Parking Aid Sens

**Repairable parts:-**Repair Rear Bumper Spoiler

**Repaint only parts:-**Rear Bumper New Part Paint K1r, L/R Parking Aid Sensnew Part Paint K1r, Rear Spoiler Cover Repair Paint Plastic, Rr Towing Eye Cover Surface Paint Plast., 2Nd Colour Uplift Surface Paint, Pre-Painting Sundry Materials, Preparation for Pre-Painting

**Specialist/Sundry charges:-**Car Care Kit, E.P.A. Charge, Adas Calibration, Sundry Part

**Remove And Refit parts:-**Gfs / Guided Function, Surround Camera Adjust, Adjust Camera Assistance System (Comp), Left Rear Wheelhouse Shell, Rear Bumper Cover, Renew Rear Bumper (Removed), Drill Rear Bumper Spoiler, Renew Rear Bumper Spoiler (Removed), Rear Bumper L/R Guide, Rear Centre Bumper Bracket, High-Voltage System Check, Adjust Radar Sensor, Align Front And Rear Vehicle, Adjust Front Camber, Adjust Front Toe, Adjust Rear Camber, Adjust Rear Toe, Parcel Shelf

**Parts to check:-**Check Veh Diag Pre Check, Check Veh Diag Post Check, Check Technical Info, Check And Quality Control

### **COST OF REPAIRS**

The repairers, Harwoods Southampton Accident Repair Cen, Unit 1, Westwood Business Park, Brunel Rd, Totton, Southampton, SO40 3WX, have compiled an estimate in the sum of £1,428.00 plus parts at manufacturer's list prices plus £331.14 for paint and materials plus £121.01 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £100.00 to £1,328.00 in their final account. The labour charge is based on 16 hours at a rate of £83.00 per hour. We have also agreed that the cost of paint and materials will be limited to £515.47. The cost of the necessary replacement parts will be approximately £564.35, the specialist/sundry charges will be £360.25, the VAT liability on this repair will amount to some £553.61 giving a total repair cost of £3,321.68 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £120.00.**

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 14/07/2025. The corresponding Glass's Guide retail value for vehicles of this type and age in the January 2026 guide is £32,974.00 at 2787 Miles, trade value is £29,637.00 and mid value is £31,305.50. We place the pre-accident value of this particular vehicle at £32,974.00 bearing in mind the condition described herein.

### **RESERVE**

We consider that a repair reserve of £3,325.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 18th March 2026, on your behalf.

### **REPAIR DURATION**

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

### **ROADWORTHY STATE**

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of