

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL


Date: 06/05/2026
Our Ref: 00035766/HASSANA
Your Ref: 45078/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Timothy Lewis**

We refer to your instructions received on **06 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: CUPRA FORMENTOR VZ2 TSI 4DRIVE S	Colour: BLACK	Speedo: 8583	Miles
Reg No: GO13UCS	Registered: Jun 2025	Type: 5 Door Hatchback	Trans: Semi-Auto
Vin No: VSSZZZKM0SR081225	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2025		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 1984		Not Tested
Air Bags Deployed: Not Known	BHP: 328.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact Rear	Incident: 01/05/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £34,898.00	Repair Cost: £2,274.02 inc VAT	(6.52% of PAV)	Roadworthy: Yes
----------------------------------	---------------------------------------	----------------	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

06/05/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Rr Bump Lwr Spoiler, Rear Bumper Diffuser, L/R Out Sensor Brkt, R/R Out Sensor Brkt, L/R Inn Sensor Brkt, R/R Inn Sensor Brkt, Car Care Kit, Sundry Parts

Repairable parts:-Rear Bumper Spoiler, Rear Bumper Diffuser

Repaint only parts:-Two Coat Metallic, Rr Bump Lwr Spoiler New Part Paint K1r, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Epa, Methods Research Specialist

Blend only parts:-L/R Bumper Surface Paint Plast., R/R Bumper Surface Paint Plast.



Remove And Refit parts:-Description, Both Rear Wheelarch Covers R + R, Rear Bumper Cover, Rear Bumper Spoiler, Renew Rear Bumper Spoiler (Removed), Drill Rear Bumper Spoiler, Renew Rear Bumper Diffusor, Drill Rear Bumper Diffuser

Parts to check:-Rear Bumper C-Member, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £899.42. The cost of the paint and materials would be £414.80, The cost of the replacement parts would be approximately £504.57, The specialist/sundry charges would be £76.23, and the VAT liability on the total would amount to some £379.00 giving a total repair cost of £2,274.02 including VAT **subject to undisclosed damage**. The labour charge is based on 10.8 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 03/06/2025. The corresponding CAP Guide (model code: 106097) adjusted retail value for vehicles of this type and age in the May 2026 guide is £34,898.00 at 8583 Miles, trade value is £32,300.00 and mid value is £33,599.00. We place the pre-accident value of this particular vehicle at £34,898.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,275.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

As no estimate has yet been obtained to repair the vehicle we have not been able to authorise repairs. Once an estimate is available we would be pleased to discuss the method and repair schedule with the chosen repairer and agree costs on your behalf, if required.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.


The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors




17_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM2REE2ODY4NDY0NzYxOUeYQTg5MTQ1MTBGOTIBQzKA-V1.jpg



3_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUMxNjZFNDczOUU0N0Y0RTgxMUEyRDQ5QzE1OUM5MzYA-V1.jpg



9_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM5NzE5NjAxRDY4RTIGNzJBRTg2RDUzMzVFVNjc3NDQA-V1.jpg



13_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNFOTIGMzgxNUUQ



imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNCOTk5MTdGRDY2QzIGMDE2MDk3NkYwMjcyMzEyQUIA-V1.jpg



7_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUMyREM2NTExmKU2REYwMTBENkU3NzgzOUNERjdGMTKA-V1.jpg



11_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM2OTBBRDIGQTk1N0FGRkRENjU3RDMYQTUwRDkxRjcA-V1.jpg



15_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNCQTAYRjU3MjhE



17_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM5NEZGMkNGQzVERTc5MDI5NTRDMDc4QTRBOUuyODEA-V1.jpg



imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNCQTAYRjU3MjhEMjNCQzA1RjA0NzMxN0ExOEQwRDEA-V1.jpg



3_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM5NEZGMkNGQzVERTc5MDI5NTRDMDc4QTRBOUuyOD EA-V1.jpg



5_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNBNUEMThCQklzMjJERjQ5OUi4MUMzRDNERtgyMEIA-V1.jpg



7_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM0MkVCNjkzREU4RDBBMjY0M0lwRTk5NzkzRjcyRUUA-V1.jpg



9_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUM1M0RGOTU2MUJGOTc5MTczNThCMzBEMURCODRCQ UEA-V1.jpg



11_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUMyOTA2REU3QUE4MzlwM0FEODEyN0QwQ0YxRkEyRUQA-V1.jpg



15_imagewamidHBgMNDQ3OTQ0NDQwNzMzFQIAEhggQUNDODU2Nzl2QTk