

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 06/05/2026
Our Ref: 00035765/HASSANA
Your Ref: 45134/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Tinotenda Gatsie**

We refer to your instructions received on **06 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: HYUNDAI I30 SE NAV BLUE DRIVE CRDI	Colour: SILVER	Speedo: 46892	Miles
Reg No: YP66VJL	Registered: Nov 2016	Type: 5 Door Hatchback	Trans: Manual
Vin No: TMAD351ULHJ364886	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2016		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Diesel		Centre Belt
Extras: Not Seen	C.C.: 1582		Not Tested
Air Bags Deployed: Not Known	BHP: 109	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Rear	Incident: 04/05/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £7,834.00	Repair Cost: £3,140.39 inc VAT	(40.09% of PAV)	Roadworthy: No

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

06/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/R Out Bumper Brkt, R/R Tyre, R/R Pressure Valve, Panel Sundries, Car Care Kit, Sundry Parts

Repairable parts:-Rear Bumper, R/R Side Panel

Repaint only parts:-Rear Bumper Repair Paint Plastic, R/R Side Panel Repair Painting <50%, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Geometry Check, Epa, Corrosion Protection Materials External

Blend only parts:-R/Out/Upp A-Pillar Surface Paint, R/Roof Rail Surface Paint

Remove And Refit parts:-Description, Rear Bumper, Right Rear Wheelhouse Shell, Right Rear Wheel, Rear Wheel/Wheels Add Work, R/R Tyre, Corrosion Prote To 1St Panel

Parts to check:-R/R Wheel, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vaccum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,415.76. The cost of the paint and materials would be £882.99, The cost of the replacement parts would be approximately £158.98, The specialist/sundry charges would be £159.26, and the VAT liability on the total would amount to some £523.40 giving a total repair cost of £3,140.39 including VAT **subject to undisclosed damage**. The labour charge is based on 17 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 16/11/2016. The corresponding Cazana Guide (model code: 19111) adjusted retail value for vehicles of this type and age in the May 2026 guide is £7,834.00 at 46892 Miles, trade value is £6,502.00 and mid value is £7,168.00. We place the pre-accident value of this particular vehicle at £7,834.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,150.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

As no estimate has yet been obtained to repair the vehicle we have not been able to authorise repairs. Once an estimate is available we would be pleased to discuss the method and repair schedule with the chosen repairer and agree costs on your behalf, if required.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to wheel impact.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.


For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors



11_CLVrearnearside45134jpeg-V1.jpeg



ClientvehicleVINNumberjpg-V1.jpg



2 ClientVehicleRegistrationjpg-V1.jpg



3 ClientVehicleRearjpg-V1.jpg



4_ClientVehicleSideViewjpg-V1.jpg




5_ClientVehicleSideView2jpg-V1.jpg



6_ClientVehicleoffside-V1.jpg



7_ClientVehicleDamages2jpg-V1.jpg



8_ClientVehicleDashboardjpg-V1.jpgg



9_CLVdamage45134jpeg-V1.jpeg



10 CLVdamage245134jpeg-V1.jpeg