


QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 05/05/2026
Our Ref: 00035682/NOELB
Your Ref: 45080/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mrs Susan Neale**

We refer to your instructions received on **05 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MINI COOPER S EXCLUSIVE	Colour: SILVER	Speedo: 14841	Miles
Reg No: BK22FSN	Registered: May 2022	Type: 3 Door Hatchback	Trans: Automatic
Vin No: WMW52DH0402S82267	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2022		
Brakes: Not Known	Tax Exp: 		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1998	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Air Bags Deployed: Not Known	BHP: 175.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Damage: Light to Moderate Collision/Impact Front	Incident: 01/05/2026		
Vehicle Value: £20,352.00		Repair Cost: £2,660.57 inc VAT	(13.07% of PAV)
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the front.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

05/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper Cover, Frt Towing Eye Cover, L/F Impact Damper, R/F Impact Damper, R/F Lwr Bumper Cover, Grille Trim Frame, Upp Rad Grille Mldg, Sundry Parts

Repaint only parts:-Three Coat Metallic, Frt Towing Eye Covernew Part Paint K1r, R/F Lwr Bumper Covernew Part Paint K1r, Polish De Nib, Preparation For Pre-Painting

Specialist/Sundry charges:-Vehicle Care Kit, Bs10125, Epa, Repair Method

Blend only parts:-L/F Wing Surface Paint, R/F Wing Surface Paint

Remove And Refit parts:-Description, Add/Time For Main Work, Strip + Retrim For Painting Of The, Strip + Retrim For Painting Of The, Front Bumper, Front Lower Bumper Carrier, Renew Front Bumper Covering, Road Test Qc, Vacuum Wash, Clean Charge Pre Estimate, Vehicle Shut Down
Parts to check:-Veh Diag Post, Veh Diag Pre

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,184.79. The cost of the paint and materials would be £506.41, The cost of the replacement parts would be approximately £421.94, The specialist/sundry charges would be £104.00, and the VAT liability on the total would amount to some £443.43 giving a total repair cost of £2,660.57 including VAT **subject to undisclosed damage**. The labour charge is based on 14.23 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/05/2022. The corresponding Cazana Guide (model code: 8045043) adjusted retail value for vehicles of this type and age in the May 2026 guide is £20,352.00 at 14841 Miles, trade value is £16,078.00 and mid value is £18,215.00. We place the pre-accident value of this particular vehicle at £20,352.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,675.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Noel Barnes Dip VDAAQP
Exclusive Vehicle Assessors



Clientvehicledamages2-V1.jpg



2_Clientvehicledamages-V1.jpg



3_Clientvehicleregistration-V1.jpg



4_CLVOSF-V1.jpg



5_CLVNSR-V1.jpg



1_Mileage-V1.jpg



9_VIN-V1.jpg