Public Building Fund Deferred Maintenance, Renovation, FY2024 Request: \$6,167,000 **Repair and Equipment** Reference No: AMD 49602 **AP/AL:** Appropriation **Project Type:** Deferred Maintenance Category: General Government Location: Statewide **House District:** Statewide (HD 1 - 40) **Impact House District:** Statewide (HD 1 - 40) Contact: Dom Pannone **Brief Summary and Statement of Need:** Address deferred maintenance needs in the Atwood Building, the Fairbanks Regional Office Building. the Juneau State Office Building, the Palmer State Office Building, the Alaska Office Building, the Nome State Office Building, and the 2nd & Gold Garage. Funding: FY2024 FY2025 FY2026 FY2027 FY2028 FY2029 1147 \$6,167,000 \$6,167,000 **PublicBldg** \$6,167,000 \$0 \$0 \$0 \$0 \$0 \$6,167,000 Total: ☐ State Match Required ☐ One-Time Project Phased - new Phased - underway Ongoing 0% = Minimum State Match % Required Amendment Mental Health Bill **Operating & Maintenance Costs:** Amount Staff **Project Development:** 0 0 Ongoing Operating: 0 0 One-Time Startup: 0 0 Totals: 0

Prior Funding History / Additional Information:

Sec11 Ch1 SLA2021 P106 L28 HB69 \$5,946,000 Sec1 Ch3 SLA2019 P2 L10 SB19 \$4,500,000 Sec1 Ch19 SLA2018 P2 L10 SB142 \$4,950,000 Sec1 Ch1 SLA2017 P2 L14 SB23 \$4,500,000 Sec1 Ch2 SLA2016 P2 L10 SB138 \$4,000,000 Sec1 Ch38 SLA2015 P2 L10 SB26 \$3,000,000 Sec1 Ch18 SLA2014 P2 L18 SB119 \$4,000,000

Project Description/Justification:

Public Building Fund (PBF) Allocated Projects

| Project Title | Project Description | Project Cost |
|------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|--------------|
| Alaska Office Building - Roof Replacement | Complete roof repair by replacement. Roof has exceeded its life span and needs replacement. #1 priority from FY 20. | \$1,500.0 |
| Alaska Office Building - Window Replacement | Replace windows in elevator lobby areas (3 floors). Wooden window frames are rotting and unsecured. | \$200.0 |

Public Building Fund Deferred Maintenance, Renovation, FY2024 Request: \$6,167,000 **Repair and Equipment** Reference No: AMD 49602 Atwood Building -Replace all old pneumatic controls with \$210.0 Old Pneumatic Control Siemens digital controls. Complete removal of pneumatic controls will allow Replacement for better HVAC control. Replace outdated Fire Alarm panel. Fairbanks Regional \$300.0 Office Building -This is a life safety issue for building Fire Alarm Panel occupants. Certified technicians performing annual inspections have relayed concern of future failure. Fairbanks Regional Update/Replace dated fire suppression \$400.0 system components and backflow Office Building -Sprinkler System preventer for code compliance. Replacement Fairbanks Regional Replace loading dock (Governor's \$300.0 Office Building entrance). Concrete is spalled and crumbled; Rebar exposed. Temporary Loading Dock Replacement repairs continue to be made but do not last. Lack of support of cantilever is a high concern. Juneau State Office Replace elevator fire curtains on all \$250.0 Building floors. Existing curtains do not function Elevator Fire Curtain correctly. Replacement Juneau State Office Perform Structure Assessment. \$550.0 Building -Replace atrium windows and seals as Atrium Window needed; replace gutters and add Replacement and flashing (3 sets). Gutters and flashing Updates prevent flood/storm damage. Linny Pacillo Garage -Fixtures in the stairwell are no longer \$120.0 Stairwell Lighting manufactured for replacement and Upgrades failing at a high rate. Nome State Office Complete roof repair by replacement. \$1,387.0 Roof has exceeded its life span and Building -Roof Replacement needs replacement. Palmer State Office The dry systems are deteriorating and \$400.0 Building rotting from the inside out. Replace Awning Fire systems. Suppression System Replacement Palmer State Office The 3rd boiler is isolated and \$50.0 Building nonfunctional until Replace Cracked sections are replaced. **Boiler Sections** Palmer State Office The 10,000-gallon UST is single walled \$300.0 Building and 40 years old and very likely to **UST Removal** corrode, leak and contaminate

| Public Building Fund Deferred Maintenance, Renovation, Repair and Equipment | | FY2024 Request: Reference No: | \$6,167,000 AMD 49602 |
|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|--------------------------|
| Amendment | surrounding ground. Industry standard is double walled, above ground. Assessment and design are needed. | | |
| 2nd & Gold Garage - Design for Repair | Needed repairs have been identified but need funding for Design and cost estimate to calculate cost and funding request for project. | \$200.0 | |
| Total PBF Allocated | | \$6.167.0 | |