Date: 5/ 7/2014 01:52 PM

Estimate ID: 70720
Estimate Version: 0
Preliminary
Profile ID: * A1

Dort Type/

A-1 AUTO BODY LTD.

5304 - 1A STREET S.E., CALGARY, AB T2H 1J2 (403) 253-7867 Fax: (403) 252-7248

Damage Assessed By: MIKE. B @A1AUTOBODY Appraised For: C/P

Type of Loss: Collision

Payer: Customer Deductible: UNKNOWN

Claim Number: C/P-LT RR DOOR

Owner: MIKE GEE

Address: 23 WALNUT DR SW, CALGARY, AB Telephone: Home Phone: (403) 589-0500

Mitchell Service: 911093

Description: 2009 Honda Pilot EX Vehicle Production Date: 6/08

Mileage: 120,000

OEM/ALT: O Search Code: None

Color: GREY

Entry

Lahor

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW

REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, REAR (DUAL-ZONE) ACTE ESCAPIC STEERING COLUMN, ANTIL OCK PRAKE SYS. TRACTION CONTROL. FOR LIGHTS

TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS

ALUM/ALLOY WHEELS, AUXILIARY INPUT, SATELLITE RADIO, TOW HITCH RECEIVER

FRONT AIR DAM, TINTED GLASS, AUTO AIR CONDITION, TRIP COMPUTER THIRD ROW SPLIT BENCH SEAT, SUBWOOFER, UNIVERSAL GARAGE DOOR OPENER

THIRD ROW REMOVABLE SEAT, VARIABLE ASSISTED STEERING, SIDE AIRBAGS
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS

DAYTIME RUNNING LIGHTS, AM/FM STEREO CD CHANGER/MP3 PLAYER

I ina Itam

ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS
POWER LIFTGATE\TRUNK, REAR AC & HEATER, REAR SPOILER, REAR WINDOW WIPER
SECOND ROW SPLIT FOLDING BENCH SEAT, STEERING WHEEL AUDIO CONTROLS

Item	Number	Labor Type	Operation	Description	Part Type/ Part Number		Labor Units
4	102749	REF	BLEND	L Roof Rail			0.6 #
2	102647	REF	BLEND	L Frt Door Outside		С	1.0
3	102659	BDY	REMOVE/INSTALL	L Frt Rear View Mirror			INC
4	102661	BDY	REMOVE/INSTALL	L Frt Otr Belt Moulding			0.6 #
5	101427	BDY	REMOVE/INSTALL	L Frt Door Adhesive Moulding	Existing		0.4 #r
6	AUTO	BDY	REMOVE/INSTALL	L Frt Door Trim Panel			INC
7	102671	BDY	REMOVE/INSTALL	L Frt Otr Door Handle			0.7 #
8	101610	BDY	REPAIR	L Rear Door Repair Panel	Existing		2.5*#
9	AUTO	REF	REFINISH	L Rear Door Outside		С	2.3
10	900500	BDY *	REPAIR	LT RR DOOR FRAME CHIPS	Existing		0.5*
11	102683	BDY	REMOVE/INSTALL	L Rear Otr Belt Moulding			0.7 #
12	102685	BDY	REMOVE/INSTALL	L Rear Door Garnish			0.3
13	101624	BDY	REMOVE/INSTALL	L Rear Door Adhesive Moulding	Existing		0.4 #r
14	AUTO	BDY	REMOVE/INSTALL	L Rear Door Trim Panel			INC
ES	TIMATE RE	CALL N	JMBER: 05/07/2014 13:	52:32 70720			

Mitchell Data Version: OEM: APR 14 V

Copyright (C) 1994 - 2014 Mitchell International

Software Version: 7.1.164 All Rights Reserved

Dallar

Lahor

Date: 5/ 7/2014 01:52 PM Estimate ID: 70720

Estimate ID: 7072
Estimate Version: 0
Preliminary
Profile ID: * A1

					i ione ib. Ai		
15	102695	BDY	REMOVE/INSTALL	L Rear Otr Door Handle			0.3 #
16	102708	BDY	REMOVE/INSTALL	L Roof Moulding			0.4
17	102751	REF	BLEND	L Quarter Panel Outside		С	1.0
18	102716	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.3
19	900500	BDY *	ADD'L LABOR OP	MASK LT 1/4 GLASS	Existing		0.2*
20	102712	BDY	REMOVE/INSTALL	Rear Bumper Cover			8.0
21	AUTO	REF	ADD'L OPR	Clear Coat			1.6
22	933005	BDY	ADD'L OPR	RESTORE CORROSION PROTECTION		10.00 *	0.2*
23	AUTO		ADD'L COST	Paint/Materials		240.50 *	
24	AUTO		ADD'L COST	Shop Materials		54.00 *	
25	AUTO		ADD'L COST	Hazardous Waste Disposal		7.50 *	

^{* -} Judgment Item

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Remarks

SOURCE;REPEAT D/S-N/N LESS THAN \$2000

**POSS ADDT'L 1/4 PANEL DAMAGE, VIEW WHEN APART

Estimate Totals

I.	Labor Subtotals Body Refinish	Units 8.3 6.5	Rate 70.00 70.00	Add'l Labor Amount 10.00 0.00	Sublet Amount 0.00 0.00	Totals 591.00 T 455.00 T	II.	Part Replacement Summary Total Replacement Parts Amount	Amount 0.00
	Taxable Labor GST - I Tax		@ 5.000 %		1,046.00 52.30				
	Labor Summary	14.8				1,098.30			
III.	Additional Costs Taxable Costs	; GST - I Tax	:	@ :	5.000%	Amount 302.00 15.10	IV.	Adjustments Customer Responsibility	Amount 0.00
	Total Additional Costs				317.10				
	Paint Material Init Rate = 37.			99.9, Addl Ra	ate = 22.00				
							I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total: Total GST:	1,098.30 0.00 317.10 1,415.40 67.40
							IV.	Total Adjustments: Net Total:	0.00 1,415.40

ESTIMATE RECALL NUMBER: 05/07/2014 13:52:32 70720

Mitchell Data Version: OEM: APR_14_V

Copyright (C) 1994 - 2014 Mitchell International

Software Version: 7.1.164 All Rights Reserved

^{# -} Labor Note Applies

Date: 5/ 7/2014 01:52 PM

Estimate ID: 70720 **Estimate Version:** 0 **Preliminary** Profile ID: * A1

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

5 Right Rear Corner (P)

Insurance Co: C/P

Inspection Date: 5/7/2014

Body Shop: A-1 Autobody

Address: 5304 1A St SE

Calgary, AB T2H 1J2 Telephone: (403) 253-7867 Fax Phone: (403) 252-7248

THIS IS A VISIBLE DAMAGE QUOTATION ONLY.

***** NOTICE ****

NO GUARANTEE AGAINST PAINT MATCH OR PEELING IF NECESSARY PARTS & TRIM ARE NOT REMOVED AND BLENDING TIME NOT ALLOWED.

Cycle Time Information

Repair Dates:

Start Date: Promise Date: 5/7/2014 5/7/2014

ESTIMATE RECALL NUMBER: 05/07/2014 13:52:32 70720

Mitchell Data Version: OEM: APR_14_V

Copyright (C) 1994 - 2014 Mitchell International Page 3 of 3 **Software Version:** 7.1.164

All Rights Reserved