

[new...](#) | [approve/reject](#) | [edit](#) | [page status](#)

welcome!
common documentation
library
ct tech pubs web page
ct water cooler
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
all ct products
index
[communiques pending approval](#)
customize
members

search:

advanced search
news: daily | weekly

[go offline](#) | [chat](#) | [notify](#) |
[print](#) | [tutorial](#) | [help](#)

[home](#)> [communiques](#)
[pending approval](#)

2302508 Brush Block Barrier Height

[christopher hardiman](#) ([christopher c hardiman](#)), 10/31/2002 - 02:29 pm

**Priority**

4 - Tips, Parts, Surveys, etc.

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5FFPYZ

Equipment

HSA, CT/i, LightSpeed QXi

Problem

In July, 2002, a barrier height issue was identified and corrected on SA brush blocks p/n: 2302508. A purge on GPO stock was performed; however, some of these bad blocks are still floating around in stock.

Corrective Action

Prior to installing the brush block, check to ensure that the last four digits of its Schliefring serial number are greater than is greater than 0276. If it is not greater, write the part off as DOA and return it for SWAP.

Author

Christopher C Hardiman

Revision

10/31/2002 02:29 PM

[new...](#) | [approve/reject](#) | [edit](#) | [page status](#)