

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
yms family
all ct products
index
old ct emails
[communiques pending approval](#)
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> [communiques](#)
[pending approval](#)

Axial Drive Motor FRU

christopher hardiman (christopher c hardiman), 07/19/2002 - 06:36 pm

**Priority****PROPRIETARY WARNING**

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5BYLVJ

Equipment

LightSpeed Plus, Ultra & 16

Problem

When originally structured, the axial drive motor, P/N 2235342, was listed as a FRU. The motor was not intended to be replaced by itself. The drive sprocket should have been included as part of the assembly level FRU since its placement on the motor shaft is critical and it is difficult to remove.

Corrective Action

The oversight has been corrected. When a need to replace either the sprocket or motor on a LightSpeed Plus, Ultra or 16 system has been identified, order 2235342-2. This includes the sprocket and motor as a single unit. Orders for the motor alone will be changed to the new FRU.

Author

Christopher C Hardiman

Revision

07/19/2002 06:36 PM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)