

Effectivity

The following CT Equipment is affected:

- 2266832 LightSpeed Plus Console Assembly
- 2266832-2 LightSpeed Plus Console Assembly w/D3D

Purpose

The features introduced with this new software include (but are not limited to) the following:

- Thin twin helical option
- Helical tilt option
- Recon Plus option
- Gantry field balance software
- Quality fixes (Refer to *Tips and Workaround* manual, 2243321-100, Rev 05)

Prerequisite FMIs

FMI 25275 (SCSI upgrade) and FMI 25276 (Pegasus Bd. Upgrade) must be installed on the system prior to this FMI where applicable.

Special Instructions

Learning Solutions - If the site is upgrading from H2M3 or H2M3.1 and has 3D Analysis, Navigator or DentaScan options, the appropriate Learning Solutions CD-ROM will need to be ordered from Technical Publications, as the Sherlock CDs will no longer function with H2.M4 or higher releases of software.

Order the following as needed:

- 3D Analysis and Navigator - 2292188-248 Rev.0
- DentaScan - 2292187-248 Rev.0

Furnished Materials

FMI 25277 Kit part number 2296265 includes the items listed below

Qty	Part Number	Description
1	2315837-100	FMI 25277 LightSpeed Plus 2.1 SW Upgrade Instruction Document
1	2280824-7	BOM-Serialized H2 2.1 M4 Ops and App. S/W Version 15, consisting of: • 46-302200P2 Rating Plate • 2284118-8 BOM LS Plus 2.1M4 OS and Apps Disks consisting of: - Operating System Disk #1 (2284177) - Operating System Disk #2 (2284178) - Operating System Disk #3 (2284179) - Applications Software (2284117-8)

Qty	Part Number	Description
1	2243321-100	Tips and Work-Around Manual, Rev 05
1	2281207-100	Technical Reference Manual, Rev 02
1	2243319-100	Software Installation Procedures (Load from Cold), Rev 05
1	2281208-248	LS Plus Learning and Ref. Guide CD, Rev 03
1	2305988	B7810TH- Thin Twin Helical Option consists of: 2142726 DICOM Magnetic Optical Disk 46-302200P7 rating plate
1	2305990	B7810TL- Helical Tilt Option consists of: 2142726 DICOM Magnetic Optical Disk 46-302200P7 rating plate
1	2305991	B7810RP- Recon Plus Option consists of: 2142726 DICOM Magnetic Optical Disk 46-302200P7 rating plate

Required Tools

Qty	Description	Part #
	MOD for Save State	
	Poly and QA phantoms that are at each site	
	Class M Software-Iling Package (Distributed on Tab)	
	• Iling Software Version 14	2284115-8
	• Iling Installation Manual	2243323-100, Rev 1
	Class C Software Version 14	2284116-8 (distributed on Tab)

People Power

Allow 3 hours of labor for one person to complete this FMI.

Procedure

Follow Software Load Procedures of Chapter 1, in Direction 2243319-100, *LightSpeed Plus Software Installation Procedures* (Rev 05) to complete this FMI.