

Electronic Signature Information

Name	DOC1667089
Revision	13
Type	Controlled Document
Title	MR software release matrix
Originator	212026419_xu__zhang
Release Date	06/10/2016 03:01:21 PM
Obsolete Date	

Name	Reason For Change	File Size (Bytes)
MR_Software_Release_Matrix.xlsx	MR Software Release Matrix	28891

Route	Signer	Function	Status	Comments	Completion Date
R-6619732	212435122_madhu__expedith	SW Engineering Mgr	Approve	Approved without Comments	6 Jun 2016 00:48:23 GMT
R-6619732	100012764_bela__kiraly	Serve Engineering Mgr	Approve	Approved without Comments	6 Jun 2016 13:15:47 GMT
R-6619732	212009061_peter_e_kargard	LSI	Approve	Approve	10 Jun 2016 11:56:17 GMT
R-6619732	212026419_xu__zhang	LSWI	Approve	Approved without Comments	5 Jun 2016 19:47:03 GMT

Periodic Review

There are no signatures or routes related to this business object.

Obsolesence Approval

There are no signatures or routes related to this business object.

* Printed versions are For Reference Only *

+ Indicates a task was reassigned from an original assignee

MAKE SURE THAT YOU ARE USING THE LATEST
REVISION OF THIS DOCUMENT.

The latest revision can be found at the on-line
documentation library.

The purpose of this document is to provide the
latest service pack information to the Field.

The latest service pack **MUST** be loaded on the
system. Failure to comply can result in customer
safety issues.

When using this document to determine
software revision and service pack, use
information that is contained within Table 1.

Contact the following for issues/questions related to this Matrix:

mr.sw.version.ib.core@ge.com

Table 1

Product/ Segment	Program Name	Software Version Label	Latest Safety Service Pack	Latest Software Service pack	FMI Number of Safety & last SP	Notes	Design Owner
Signa	1.x, 2.x, 3.x	1.8.13, 2.5.19, 3.3.9	None	None	NA		MKE
Signa Advantage	Signa 4.8	4.8.10	None	None	NA		MKE
Signa Horizon	Signa 5.3.2	5.3.2	None	None	NA		MKE
Signa Advantage	Signa 5.4	5.4	None	None	NA		MKE
Signa Horizon	Signa 5.4	5.4.3 / 5.4.3z	None	None	60434/60427	see note 1	MKE
Signa Advantage	Signa 5.5	5.5	None	None	NA		MKE
Signa Horizon	Signa 5.5	5.5	None	None	NA		MKE
Signa Horizon	Signa 5.6	5.6	None	None	NA		MKE
Signa Horizon	Signa 5.7	5.7	None	None	NA		MKE
Signa Horizon	Signa 5.8	5.8	None	None	NA		MKE
Resona, Resona-C, MR MAX, MR Max-C	V/R 5.71	V/R 5.71	None	None	NA		HNO
Vectra	V/R 4.13	V/R 4.11, 4.13	None	None	NA		HNO
Sierra	V/R 4.13	V/R 4.13	None	None	NA		HNO
Contour / Profile	VMX	7.67, 7.72, 7.80, 7.81, 7.82 7.84	None	SP-02	NA	See note 2	HNO
Signa Lx	8.3	83.273Q_M5_0012.a	None	None	NA		MKE
Horizon Open Speed	HFO3	HFO3.29I_M4_0320.a	SP-02	SP-02	67706		MKE
Horizon 3T	VH3	VH3.29I_M4_0339.a	None	None	NA		MKE
E2	Excite II; E2	E2.0_M4_0502.b	SP-03	SP-03	60808D		MKE
G3	Excite II; G3	G3.0_M4B_0513.a	SP-03	SP-03	60808D		MKE
Profile 5	Profile 5	PROFILE5.293a_M4_0542.a	None	SP-01	N/A	See note 3	BJG
Signa Lx	9.x	Any 9x version prior to 91.29I_M4A_0723.d	N/A	N/A	N/A	See note 4	MKE
Signa Lx	9.1	91.29I_M4A_0723.d	SP-01	SP-01	60748		MKE
Profile HD	ProfileHD	PROFILEHD.0_M4_0736.a	SP05	SP05	67816BB		BJG
Ovation 5	Ovation 5	OVATION5.293a_M4_0737.a	SP-03	SP-03	67626		BJG
Excite	Excite Plus	Any 11x version prior to 11.1_M4_0818.a	NA	NA	NA	See Note 5	MKE
Excite	Excite Plus	11.1_M4_0818.a	SP-05	SP-05	60808E		MKE
Ovation 2	MFO2	MFO2.29F_M4_0828.a	SP-01	SP-01	67619 (SP-01)		HNO
Ovation 3	MFO3	MFO3.291a_M4_0837.a	SP-02	SP-02	67620 (SP-02)		HNO
HFO5	HFO5	OPENMR5.293a_M4_0838.a	SP-05	SP-05	67815D		HNO
Excite Ovation	MFO4	OPENMR4.292a_M4_0844.a	SP-04	SP-05	67815B (SP-04) 67625B (SP-05) optional		HNO
EXCITE OpenSpeed	HFO4	OPENMR4.292a_M4_0844.a	SP-04	SP-05	67815C (SP-04) 67625C (SP-05) optional		HNO
Signa HD	HD	12.0 any revision other than M5B_0846.d	NA	NA	NA	See note 6	MKE
Signa HD	HD	12.0_M5B_0846.d	SP-02	SP-02	60808B		MKE
Ovation HD	Ovation HD	OVATIONHD.0_M4_0909.a	SP-03	SP-03	67816BC		BJG

Product/ Segment	Program Name	Software Version Label	Latest Safety Service Pack	Latest Software Service pack	FMI Number of Safety & last SP	Notes	Design Owner
HDe2	HDe2	HDE15.0_M4_0943.c	SP-08	SP-09	67816 (SP-08) 67818 (SP-09) Optional		HNO
Signa HDxt	HDx	14.0, any release revision.	SP-01	SP-01		See note 7	MKE
Signa HDxt	HDxt	15.0_M4_0910.a	SP-05	SP-05	67816AB		MKE
Signa HDxt	HDxt	15.0_M4A_0947.a	SP-04	SP-04	67816AB		MKE
Signa HDxt	HDxt	15.0_M4B_1034.a	SP-04	SP-04	67816AB		MKE
Signa HDxt	HDxt Apps	HD16.0_V01_1108.b	SP-01	SP-01	67816AB		MKE
Signa HDxt	HDxt Apps	HD16.0_V02_1131.a	SP-01	SP-03	67816AB (SP01)	See note 8	MKE
Signa HDxt	HD23 V01	HD23.0_V01_1210.a	SP-02	SP-02	60850	See Note 9	MKE
Signa HDxt	HD23 V02	HD23.0_V02_1406.a	None	SP-03	60889	See note 10	MKE
Signa HDxt	HD23 V03	HD23.0_V03_1614.b	None	None	60884D (3.0T sites) 60886A & B (1.5T sites)	See note 19	MKE
Brivo MR355, Optima MR360	HDSV	SV20.1_IB3_1213.a					
			SP-01	SP-03	67816BA (SP-01) 67915(SP-03)Optional	See note 11	BJG
Brivo MR355, Optima MR360	HDSV	SV20.1_V04_1435.a	None	None	67916 Optional		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V01_1238.b	None	SP-01	N/A		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V02_1309.a	None	SP-01	N/A		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V03_1323.a	None	None	67913		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V04_1329.b	None	SP-01	67915 (SP-01) Optional		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V05_1436.a SV23.0_V05_1404.b	None	None	67916A Optional		BJG
Brivo MR355, Optima MR360	16 Beat	SV23.0_V06_1520.a	None	None	67918A Optional		BJG
Brivo MR355, Optima MR360	Bamboo	SV23.1_EB_1507.a	None	None	67918B	See Note 13	BJG
Brivo MR355, Optima MR360	Bamboo	SV23.1_R01_1548.a	None	None	N/A		BJG
Discovery MR450, MR450w, MR750,	DVApps	DV22.0_V02_1122.a				See Note 12	
			SP-03	SP-03	67816AA		MKE
Discovery MR450wGEM	GEM	DV22.1_V01_1131.a	SP-03	SP-03	67816AA	See Note 12	MKE
Discovery MR450, MR450w, MR450wGEM, MR750, MR750w, MR750w GEM	DV23.0	DV23.0_V01_1142.a	None	SP-07		See Note 12	
					NA		MKE
Discovery MR450, MR450w, MR450wGEM, MR750, MR750w, MR750w GEM	DV23.1	DV23.1_V02_1317.c				See Note 12	
			None	None	NA		MKE
Discovery MR450, MR450w, MR450wGEM, MR750, MR750w, MR750w GEM	DV24	DV24.0_R01_1344.a					
			None	None	NA		MKE
Discovery MT750w and MR750	DV24	DV24.0_R02_1607.b					
			None	None	60884B 60884BC	See Note 18	MKE
Discovery MR750w 3.0T, Optima MR450w 1.5T	DV25	DV25.0_R01_1451.a	None	None	NA	See Note 14	MKE
Discovery MR750w 3.0T, Optima MR450w 1.5T	DV25	DV25.0_R01_1451.a	None	None	NA	See Note 14	MKE
Discovery MR750w, MR750,	DV25	DV25.0_R02_1549.b	None	SP-02	60884A for base SW 60895 for SP-02	See Note 17	MKE
Optima MR450w 1.5T	DV25	DV25.0_R02_1549.b	None	SP-02	60895 for SP-02	See Note 20	MKE
SIGNA PET/MR 3.0T	MP24	M4 MP24.0_R01_1524.a, petmr_everest.141	None	None	NA		MKE
ONI, ORTHONE 1.0		3.02	None	None	NA		MKE
ONI, MSK Extreme 1.5T		3.53	None	None	NA		MKE
ONI, Optima 430s		3.54	None	None	NA		MKE
ONI, Optima 430s		4.00, 4.01, 4.02	None	None	NA		MKE
SIGNA Creator/SIGNA Explore	SV25 R01	SV25.0_R01_1519.a	None	None	NA		BJG
SIGNA Creator/SIGNA Explore	SV25 R02	SV25.0_R02_1525.a	None	None	67918C		BJG
SIGNA Creator/SIGNA Explore	SV25 R03	SV25.0_R03_1534.a	None	None	NA		BJG
SIGNA Creator/SIGNA Explore	SV25 R04	SV25.0_R04_1543.b	None	None	67919A		BJG
SIGNA Creator/SIGNA Explore	SV25 R05	SV25.0_R05_1612.a	None	None	67920A		BJG
SIGNA Pioneer 3.0T	KIZUNA (M3)	PX25.0_EB_1529.a	None	SP-01	NA	See Note 15	HNO
SIGNA Pioneer 3.0T	KIZUNA (R01)	PX25.0_R01_1603.a					
			None	None	NA	See Note 16	HNO
Discovery MR750w 3.0T, Optima MR450w 1.5T	DV25.1	DV25.1_EA_1550.a	None	None	NA		MKE

Note 1: Any site with 5.4 software must be at 5.4.3 or 5.4.3z. If needed, order FMI 60434 or 60435

Note 2: for this release all Service packs including no service pack is acceptable

Note 3: For Profile5 SP-01 was released with forware production only, there was no FMI.

Note 4: Sites with prior versions of 9x software must update to 91.291_M4A_0723.d via FMI 60748

Note 5: Sites with prior version of 11x software must update to 11.1 via FMI 60747 and FMI 60808E

Note 6: Sites with prior versions of 12x software must update to 12.0_M5B_0846.d per FMI 60752 and FMI 60808B (SP-02)

Note 7: Sites running any version of 14.x should have upgraded to 15.x via FMI's.

Note 8: Sites with HD16.0_V02_1131.a software must be at a minimum of SP-01. FMI 60839 was an Optional FMI that introduced SP-02.

Released

Product/ Segment	Program Name	Software Version Label	Latest Safety Service Pack	Latest Software Service pack	FMI Number of Safety & last SP	Notes	Design Owner
------------------	--------------	------------------------	----------------------------	------------------------------	--------------------------------	-------	--------------

Note 9: HD23_V02 was an optional FMI and forwarded production release, HD23_V01 with SP-02 is a valid configuration

Note 10: SP-01 and SP-02 are optional. SP-03 was included in forward Production only

Note 11: SV20.1_IB3 sites must be at a minimum of SP-01. SP-03 is not required as this is an optional FMI.

Note 12: Sites should have upgraded to DV24.0_R01. Determine if customer refused upgrade FMI. If not, site can be upgraded.

Note 13: The Bamboo system with software SV_23.1 is in pilot phase. Any SW release is acceptable, Example is SV_23.1_EB_1507.a

Note 14: The MR750w and MR450w GEM systems received DV25 software via FMI 60867.

Note 15: Sites with PX25.0_EB software must update to SP-01 via FMI 68000A and FMI 68000B

Note 16: PX25.0_EB software update to PX25.0_R01_1603.a is planned via FMI68001A and FMI68001B

Note 17: Safety FMI 60884A introduced the Head SAR fix for 3.0T sites only.

Business (Non safety) FMI 60895 introduces SP-02 for DV25.0_R02 release. At this time FMI is only for MR750w sites.

Note 18: Safety FMI 60884B and 60884BC introduced the Head SAR fix for 3.0T sites only. There will be an additional FMI for 1.5T sites with DV24 software at a later date.

FMI 60884BC is for China only, FMI 60884B is for all other countries. Both FMI's will release on March 3, 2016

Note 19: Safety FMI 60884D introduced Head SAR fix for 3.0T sites only.

Business (Non safety) FMI 60886A and 60886B introduced non-safety fixes for 1.5T

Note 20: FMI 60895 is needed for all MR450w sites that shipped as forward production with release DV25.0_R02 software.

If a 1.5T site is running DV25.0_R01 software there is no plan to update to DV25.0_R02 at this time, will remain at DV25.0_R01.

Document: MR Software Release Matrix

Document number: DOC1667089

Revision No	What changed	Reason for change
1	Initial release	Initial release
2	Added note5. modified note4. Removed the extended labels from base version.	Corrected errors found with initial release
3	Improvements from Field Feedback	Improvements from Field Feedback
4	add SIGNA Creator/SIGNA Explore info	new product info
5	Added Pole column in IB MR Products tab and instruction tab; Replaced MP24 M3 version with M4; Updated HD23 V02 latest Service Pack version as SP2	To combine IB and NPI program list in this document such that DOC1140322 will directly refer to this doc; NPI milestone and new Service pack release
6	Added SIGNA Pioneer info	new product info
7	Updated product name from SIGNA Pioneer to SIGNA Pioneer 3.0T Updated PX25 EB Latest Service Pack version as SP1	Updated product name to distinguish between 3.0T and 1.5T Updated Service Pack info
8	Added DV25.1 information	M3 release of DV25.1
9	Added PX25.0_R01 information.	R01 release of PX25.0
10	Updated HD23 Service Pack and updated DV24 and DV25 releases.	Head SAR FMI's
11	Updated for SV23/SV25 software release information	Updated for SV23/SV25 software release information
12	Updated for HDe2 SP09 release.	SP09 release of HDe2.
13	Updated for HD23 V03 and DV25 R02 SP2	Updated for HD23 V03 and DV25 R02 SP2

Author
Khagesh Sailada
Khagesh Sailada
Peter Kargard
Xu Zhang
Diao Zhuo
Peter Kargard
Xu Zhang
Masako Ohara
Masako Ohara
Anuradha
Subramanian
Hiroataka Matsuura
Peter Kargard
Xu Zhang
Yang Ming
Shinya Sakuma
Peter Kargard
Xu Zhang

Step #	Responsibilities	Role
1	Add new program to "MR Product" sheet when the program has M3, M4* or service pack is released to the field and fill the columns C, D, E, F, G and J.	LSWI
2	Update Column H and I for "MR Product" sheet in step 1	LSI
3	Send the document for review and collect feedback.	LSWI
4	Route the document for appoval	LSWI
5	Document approval	Pole SW Engg Mgr & Pole Service Engg Mgr
6	Send field communication.	LSI

* when the program reach M4, revise the M3 SW version with the latest version.