

[new...](#) | [page status](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
yms family
all ct products
index
old ct emails
[communiques pending approval](#)
communicate change requests
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> [communiques](#)
[pending approval](#)

Weakly Attached LASER Alignment Light Window

christopher hardiman (christopher c hardiman), 09/17/2002 - 09:25 am

**Priority**

4 - Tips, Parts, Surveys, etc.

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5E3JP2

Equipment

LightSpeed Ultra, Plus & 16

Problem

The field and manufacturing have noticed that the front cover vendor is attaching the LASER alignment light windows quite weakly. This is being addressed in forward production; however, the total installed base exposure is unknown. The windows will not fall out during routine use of the system, but may be dislodged during cleaning of the covers.

Solution

Since the FRU is the front cover, it is advised that the FE utilize any commonly available two-part epoxy to re-attach any window that becomes so dislodged. Be careful not to get the epoxy on any window surfaces where the LASER must shine through.

Author

Christopher C Hardiman

Revision

09/17/2002 09:25 AM

[new...](#) | [page status](#)