

Effectivity

All LightSpeed QX/i Systems with Gantry Model Number 2180482.

H1.3 M4 software is required on this system prior to loading the H1.3 eFlextrial Patch software.

To verify that this software is loaded on the system, check *showprods*.

showprods <ENTER>

The above line shows the Product at 1.3M4 software. If the above line does not contain the string **10.5.x.x.x.xH1.3M4**, the scanner does not have the most recent 1.3 software and FMI 25269 will have to be completed prior to implementing this software patch.

If a system has had a previous version of this patch software loaded (as an external evaluation or pilot site), the previous version of the patch will have to be uninstalled prior to loading the final version included in this FMI kit. Uninstall instructions are included in the load instruction document included in this FMI package. Please see the Patch Load Instructions (2300753-100 Rev 2) included in this kit for further information.

NOTICE: The above checks should be done if the FMI is being loaded on site. The preferred method of loading this FMI is via a remote download. If the remote download is used, the download script performs the above checks automatically. If a previous version of the patch is on the system, or the incorrect version of software is detected, the download will not be completed and a message will be returned to the requestor.

Purpose

The purpose of 1.3 eFlexTrial is to implement eFlextrial on H1 systems, to correct 2 software bugs that can cause ScanRX crashes, and correct some Collimator Cal and Thin Twin cal issues on the H1.3 platform.

Prerequisite FMI's

None.

Related FMI's

None.

Furnished Materials

FMI Kit Part Number 2310071 includes the items listed below

Qty	Description	Part #
1	FMI Document Rev 2	2300752-100
1	Software Patch Load Instructions Rev 2	2300753-100
1	Intro Planner Document Rev 0	2300754-100
1	LightSpeed QX/i Rev 1.3 Patch Software CDROM	2308925-2
1	Customer Letter Rev 1	2315287-100
1	Rating Plate	

Tools Required

None

People Power

Labor Estimates: 1 hour (if loaded on site, remote download possible)

Travel Estimates: 1 hour

Procedure

Install the FMI per direction 2300753-100 - 1.3 Software Patch Load Instructions. If the system has connectivity, it is recommended that the remote download and verification process outlined in the Patch Load Instructions be used. If the download and remote verification process is used, the Rating Plate, Customer Letter, and Software CD containing the software can be delivered to the site during the next regularly scheduled customer visit.

FMI Completion

Complete the Product Locator information cards and return.

Fill out and return the FMI Completion Certification Report paperwork (or electronically close your FMI dispatch) in accordance with your local procedure.