

**ADMINISTRATIVE INFORMATION****FMI No: 25302****FMI Title: LightSpeed Plus/Ultra Ver 303 Patch S/W**

FMI TYPE	CHARGE CODES	IMPLEMENTATION DATES
☐ Mandatory Safety	GEMS - AM:	Issue Date:
☒ Mandatory	GEMS - E:	
☐ Mandatory on Request	GEMS - A:	Close Date:

☒ Staged FMI	Customer List provided by FMI Administration. If you identify additional units within effectivity range, but they are not shown on the customer list, contact FMI Administration in your Pole.
☒	Parts and any special tools are furnished automatically. To address shortages and ordering exceptions, contact FMI Administration in your Pole.
☐	Parts Ordering: GEMS - Americas, Contact your Region logistics coordinator GEMS - Europe, Order FMI kits from GPO/EPL Buc GEMS - Asia, Contact your region logistics coordinator
☐	No Parts are required to complete this FMI.
☒ Batch with	FMI 25300 (when applicable)
	To minimize costs, combine implementation of this FMI with the FMI's listed for all customers where the effectivity is the same (Please see your customer lists).
☐ Non-Staged	No Customer List is provided. Each service location must identify affected units, and place part orders as indicated in the Special Instructions.

Technical Support

GEMS - Americas	GEMS - Europe	GEMS - Asia
GE Medical Systems Insite Center (414) 524-5300 800-321-7973 Milwaukee, WI 53201, USA	GEMS - E / ESC BP34 F 78533 BUC CEDEX, FRANCE Tel: (33 1) 39 20 00 07 or ESC Fax: (33 1) 30 70 99 70	Asia Support Center Phone: 81-426-56-0033 Fax: 81-426-48-2905

Special Instructions:

This FMI applies software model number 2305095-5 on systems manufactured before April 5, 2002. To assure complete coverage, the gantry is being used as the tracking number.

Unit Tracked: 2281177**FMI Instructions Part No.: 2337596-100****Do NOT leave unsecured on site**

FMI Completion Certification Report

Mail To

GEMS - Americas	GEMS - Europe	
G.E. Medical Systems Attn: FMI Admin. W-523 P.O. Box 414 Milwaukee, WI 53201	GEMS - Europe FMI Admin. 322 BP34 F78533 Buc Cedex, France	Send to your Country FMI or Service Administrator

FMI No.: 25302

FMI Title: LightSpeed Plus/Ultra Ver 303 Patch S/W

Customer Full Name: _____

Number and Street Address: _____

City and Country: _____

Country Code

Site Number

System I.D.

Unit Tracked:

Model Number	Serial Number	Compl. Date DD/MM/YY	FMI Comp. Code	Service Hours	
				Labor	Travel

FMI Completion Code

1. Modification Complete or previously modified.
2. FMI not required per FMI instruction.
3. Not modified. Unit in storage. FMI kit returned to stock.
4. Modification refused or equipment altered. Customer signature and title required.
5. Unit location unknown or unit not in area. Product Locator notified.

Customer Refusal or Equipment Altered - Modification Pending.

Installer
Comments _____

Effectivity

All LightSpeed Plus/Ultra systems with gantry model number 2281177 manufactured before April 5, 2002.

H3_M4 LightSpeed Plus Ultra version 303 system software (2305095-5) is required to be loaded before this patch can be loaded. See Verification Procedure to check current software version.

Purpose

The purpose of this FMI is to fix to critical problems found with the version 303 software.

1. While filming and performing other operations, some images on the film may only be half displayed.
2. Under heavy processing simultaneity processes, the display functions can become slow and appear to be none functioning.

Prerequisite FMIs

- FMI 25300 LightSpeed Plus/Ultra Version 303 Software Release

Related FMIs

None

Furnished Materials

FMI Kit Part number **2337901** includes the items listed below:

Qty	Description	Part #
1	FMI Document	2337596-100
1	LightSpeed Plus/Ultra V303 Patch	2337222
1	LightSpeed Plus/Ultra V303 Patch S/W Load Instructions	2337856-100
1	LightSpeed Plus/Ultra Applications Tips & Precautions	2296447-100

Tool Required

No special tools required

People Power

Labor Estimates: 1 hour (if loaded on site, remote download possible)

Travel Estimates: 1 hour

Procedure

Install the software patch per direction 2337856-100 LightSpeed Plus/Ultra V303 Patch S/W Load Instructions. If the systems has connectivity, it is recommended that the remote download and verification process outlined in the instructions be used. If the download and remote verification process is used, the CD and documents can be delivered to the site during the next regularly scheduled customer visit.

When delivering the documents and CD to the site, review the document 2296447-100 for new software features and precautions with the customer.

FMI Completion

Fill out and return the FMI Completion Certification Report paperwork (or electronically close your FMI dispatch) in accordance with your local procedure.

Special Notes

During the load of the version 303 software, the values and order of WW and WL are incorrect for Image Works. This causes the function key WW and WL in ExamRx Display and Image Works to not match. Order of Preferences don't match label of Function keys F6-F11.

To correct this per form the following:

1. Correct the List order.
 - A. Select Image Works
 - B. Select Viewer
 - C. Select User Preferences
 - D. From top to bottom the list should be as follows:
 - Abdomen (F6)
 - Head (F7)
 - Lung (F8)
 - Mediastinum (F9)
 - Spine (F10)
 - Vertebra (F11)
2. Set the correct WW and WL settings for each function key
 - A. Select ExamRX Display
 - B. Place a free viewport in primary focus
 - C. Display an image if desired
 - D. Adjust the WW and WL to the desired value for Abdomen either by the accelerator line or by using the mouse.
 - E. Hold the shift key down and press F6 to stroe this value.
 - F. Repeat steps C through E for each of the other function keys (F7-F11)

Preference Key	Window Width	Window Level
Abdomen (F6)	400	40
Head (F7)	100	35
Lung (F8)	2000	-700
Mediastinum (F9)	350	40
Spine (F10)	300	35
Vertebra (F11)	2000	250

Table 1 - Typical WW and WL values

This page left intentionally blank