

FCT SERVICE NOTE SN06112814a

Class C information is Property of GE.

Date: November 28, 2006

Subject: VCT Detector Module Feedback Form.

Effectivity: 7.x VCT systems

Details:

Most VCT detector modules returned are being labeled as No Defect Found or have loose module flex screws (See SN06101714a). There is no information regarding the failure mode observed in the field that can be tied to a particular module with the current reporting methods to aid in root cause analysis of returned modules.

Resolution:

In order to make sure that no failure modes are missed during retest and repair of returned modules, a data form is being introduced and included with the FRU. This form is a variation of the form already in place for the Watson Detectors that has helped significantly in root cause analysis of returned Watson detectors over the last 3 years.

This information is important for root cause analysis of failed parts to improve the quality of processes and repaired FRU parts. The VCT Digital Module Return Form is included with the FRU and available online. Hyperlink is below and is included on the form at the top.

http://data.supportcentral.ge.com/data/sup_document.asp?id=1530991&type=doc

Please use the form for all module replacements. Use the online version whenever possible to alleviate typing errors in the repair facility as there are further electronic sections used by the repair facility to track the root cause analysis tied to each module and used for further automated tracking.

Attached is a copy of the form for reference.

Note: the reference to Inner modules is the center 5 modules 27-31, outer modules is everything else.

"IFB" is referencing the DIFB. A future copy of the form should have these references fixed. I added a few notes on the form below to clarify these changes.

Steve Merritt
FCT Service Engineering

GE Healthcare Functional CT (FCT) Class C eService Notes are copyright (c) to General Electric Company Inc with all rights reserved.
 Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare
 Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE
 Healthcare is prohibited.
 Duplication and distribution of any class of FCT eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

VCT Digital Module Return Form	
Please use this form to document critical information about the failure and return it with the Digital Modules Kit.	
You may also submit the information online using a form at the support central address below.	
http://data.supportcentral.ge.com/data/sup_document.asp?id=1530991&type=doc	
Part Information (Section A)	
FIELD ENGINEER: Please enter identification of nonconforming product below.	
Date	
System ID Example(s): 200400CN1	
Detector Serial Number Example(s): 2004CD1	
Part Number Example(s): Inner Module Outer Module	Center (27-31) ☐ Inner Module ☐ Outer Module
Serial Number Please enter the Module Serial Number. Example: F2303.3016	
Module Location Enter the Location in the Detector the Module was removed from (1-57).	

GE Healthcare Functional CT (FCT) Class C eService Notes are copyright (c) to General Electric Company Inc with all rights reserved.
 Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare
 Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE
 Healthcare is prohibited.
 Duplication and distribution of any class of FCT eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

Reason for Detector Replacement (Section B)	
FIELD ENGINEER: Please enter information on the evaluation of nonconforming product below.	
Image Failure Type Example(s): Ring Band Streaks CA/CS	☐ Ring ☐ Band ☐ Streaks ☐ Center Artifact/Center Smudge ☐ Other
Performance Failure Type: Examples: DAS Interconnect, Open Pixel, Shorted Pixel.	☐ DAS Interconnect ☐ DAS Leakage ☐ Pop Noise/Micro ☐ Open ☐ Short
Failing Pixel(s) Enter Channel and Slice of Failing Pixels: Example(s): 14,32A; 1,16B	Typically found by Fastcal, seen in gesyslog
Technique Type (kv/ma) Example(s)(kv/ma): 80/40 120/200 140/140	
Intermittent Failure Example(s): Yes No	☐ Yes ☐ No
Comments Please provide additional information if required.	
Troubleshooting Components (Section C)	
FIELD ENGINEER: Please enter information on the Troubleshooting of nonconforming product.	
Time of Troubleshooting: Example(s)(Hour)(Minutes)(AM or PM): 01 51 PM	
Date of Troubleshooting Please use calendar button to select Date of Troubleshooting	
IFB Replaced? Was an IFB replaced during troubleshooting?	☐ Yes ☐ No IFB = DIFB
If so, IFB Number	
DCB Replaced? Was the DCB replaced during trouble shooting?	☐ Yes ☐ No
List Replaced Parts Record all parts replaced during trouble shooting here (enter: NONE, if none were replaced)	
FIELD ENGINEER: You have completed request form, Please return this form with the Module or Enter the data via the web form. http://data.supportcentral.ge.com/data/sup_document.asp?id=1530991&type=doc	