

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare. Disclosure to persons not employed by GE Healthcare or not in possession of an Advanced Service Agreement with GE Healthcare is prohibited. Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

**MI&CT eSERVICE NOTE
SN07111513a**

Class C information. Property of GE Healthcare

This short-term informational note is invalid 6 months after the issue date.

Date: 11/15/07

Subject: Field personnel cannot repair threaded inserts in the Field

Effectivity: Lightspeed 16 (4.X)

Details:

A Field Replaceable Unit (FRU) component was received on site with damaged threaded inserts and an attempt was made to repair the threaded inserts and use the FRU component rather than replace the defective FRU component.

Resolution:

While servicing GE Healthcare equipment, if there is reason to doubt the integrity of any component, do NOT attempt to use (or reuse) the component. The correct action is to always order a new component. Never attempt to repair threaded inserts or defective FRU components in the Field.

Affected Service Publication: Direction 5114045-800 Rev 8, LightSpeed 4.x Service Methods

Tracking Number (PQR/SPR/ECR): PSR 13124146

David Bock
MICT Mechanical Design Engineer