

[new...](#) | [approve/reject](#) | [edit](#) | [page status](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
yms family
all ct products
index
old ct emails
[communiques pending approval](#)
communicate change requests
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> [communiques](#)
[pending approval](#)

Gantry Top Cover Switch Pad Adhesive

christopher hardiman (christopher c hardiman), 09/26/2002 - 11:04 am

**Priority**

3 - Troubleshooting Information

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5ECLN3

Equipment

LightSpeed Plus, Ultra & 16

Problem

Manufacturing has noticed that the top cover switch actuation pads on the gantry top covers (mark #8 in below drawing) have been poorly attached recently. If the adhesive comes free, the pad could fall into the fan and create noise.

Solution

It is recommended that the field inspect their top covers for the presence of these pads and ensure that they are firmly attached. If it should fall off, simply glue them back in place with a commonly available two-part epoxy.

You can download any of the files below by dragging them to your Windows desktop.
To open a file for reading, double-click it.

**Author**

Christopher C Hardiman

Revision

09/26/2002 11:04 AM

[new...](#) | [approve/reject](#) | [edit](#) | [page status](#)