

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)



welcome!
 common documentation
 library
 ct tech pubs web page
 ct water cooler
 surveys
 9800/hla
 highspeed family (us)
 ct/i
 lightspeed family
 all ct products
 index
[communiques pending approval](#)
 customize
 members

search:



advanced search
 news: daily | weekly

go offline | chat | notify |
 print | tutorial | help

home> [communiques](#)
[pending approval](#)

Scan analysis tool does not work

[joseph steltenpohl \(joseph steltenpohl\)](#), 11/14/2002 - 11:52 am

[draft in progress](#) | [published version](#)

Priority

3 - Troubleshooting Information

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
 Disclosure to third parties prohibited.

Communique Number

MQUE-5FTQLF

Equipment

2.2, 2.3m3 (ls2002m3), 300 (H3M4), 3.1m3 (ls2002m3)

Problem

Unable to launch Scan Analysis Tool on LightSpeed

Solution

Found that hostname had an underscore "_". Changing the hostname on the system to one without an underscore fixed the problem. Example of a GOOD hostname - ctplus Example of a BAD hostname - ct_plus This is know to be a problem in 2.2, 2.3m3 (ls2002m3), 300 (H3M4), 3.1m3 (ls2002m3) Please do not include an underscore in the hostname during installation of LightSpeed systems. refer to CT-SOLUTION-028818

Author

Joseph Steltenpohl

Revision

11/14/2002 11:52 AM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

