

TECHNICAL BULLETIN



MODEL/DERIVATIVE:
Mini

Bulletin N°: **0051**
CDS. ref: **X8507bu**
Issue: **1**
Date: **5.07.2000**

AFFECTED RANGE:
All vehicles

PROBLEM:
BATTERY LEADS LOOSE - LOW MILEAGE VEHICLES

- Owner reports vehicle will not start or vehicle suffers electrical failure.
- Recent feedback from Rover Assistance have shown a significant increase in this type of failure occurring soon after vehicle purchase.

CAUSE:
Battery leads not checked for tightness at PDI. Vehicle may have had battery disconnected prior to sale and temporarily re-connected to allow transfer.

ACTION:
**While carrying out routine under bonnet PDI checks, it is important that both battery leads are checked for tightness.
Failure to ensure this can result in customer dissatisfaction early in the vehicle life.**

Please ensure that all technicians and routine service staff are aware of this important requirement.

Related information:
See also 'DEALER COMMUNICATION' letter SL/005/2000 (sent to UK dealers only) dated 3 March 2000.

PARTS INFORMATION:
Not applicable

WARRANTY CLAIMS:
Not applicable