





| Signed | Alt+Shift+S |
|-----------------------------|--|
| Unsigned | Alt+Shift+U |
| Hex - ASCII | Alt+Shift+H |
| Binary | Alt+Shift+B |
| 32 Bit signed | > |
| 32 Bit Unsigned | > |
| 64 Bit Signed | > |
| 64 Bit Unsigned | > |
| 32 Bit Float | > |
| 64 Bit Double | > |
| Communication | |
| Real time Charting | Alt + R |
| Link to Chart | > |
| Colors | Alt+Shift+C |
| Font | Alt+Shift+F |
| Scaling | Ctrl+Shift+S |
| PLC Addresses (Base 1) | |
| Protocol Addresses (Base 0) | |
| Error Counters | F11 |
| | Hex - ASCII Binary 32 Bit signed 32 Bit Unsigned 64 Bit Signed 64 Bit Unsigned 32 Bit Float 64 Bit Double Communication Real time Charting Link to Chart Colors Font Scaling PLC Addresses (Base 1) Protocol Addresses (Base 0) |

