Reducing Production Costs

Donald J. Wheeler

Fellow American Statistical Association Fellow American Society for Quality



Contents

	About the Author	ix
	Acknowledgments	\boldsymbol{x}
	Preface	xi
PART ONI	E: INTRODUCTION	
11111 011	5. 11.11.10.2 C C11.01.	
Chapter 1	The Nature of Data	1
	1.1 Cause-and-Effect Relationships	1
	1.2 Identifying Control Factors	5
	1.3 Assignable Causes and Common Causes	7
	1.4 Two Ways to Improve a Process	10
	1.5 The Fork in the Road to Process Improvement	12
	1.6 Summary	14
Chapter 2	The Analysis of Observational Data	15
	2.1 Observational Studies versus Experimental Studies	15
	2.2 Process Behavior Charts	17
	2.3 Average and Range Charts	20
	2.4 The Chart for Individual Values and Moving Ranges	24
	2.5 Caution regarding Software	29
	2.6 How Process Behavior Charts Work	29
	2.7 Using Process Behavior Charts for Continual Improvement	31
Chapter 3	The Opportunities	41
	3.1 Performance and Potential	41
	3.2 Capability Indexes	45
	3.3 Performance Indexes	47
	3.4 The Gaps	49
	3.5 The Two Definitions of Trouble	50
	3.6 The Four Possibilities	52
	3.7 Summary	56
Chapter 4	The Costs of Using Conforming Product	57
•	4.1 The Problem of Production	57
	4.2 Tighten the Specifications: The Center Cut Approach	60
	4.3 Random Assembly with the Original Specifications	61
	4.4 Tweaking the Target Value for the Bearing Diameter	63
	4.5 Pre-Sorting the Parts	65
	4.6 The Traditional Approaches to Production	66
	4.7 The Effects of Reducing Variation at the Source	68
	4.8 Summary	73

PART TWO: USING EXCESS COSTS

Chapter 5	From Capabilities to Excess Costs	75
	5.1 The Effective Cost of Production and Use	75
	5.2 The Gaps between Performance and Potential	80
	5.3 The Batch Weight Data	82
	5.4 The Methanol Percentages	87
	5.5 Tokai Rika Revisited	89
	5.6 The Cover Examples	91
	5.7 The Tables for Two-Sided Specifications	92
Chapter 6	Economic Operation	93
	6.1 The Excess Costs of Production	93
	6.2 The Excess Costs of Use	94
	6.3 The Effective Cost of Production and Use	95
	6.4 The Zone of Economic Operation	98
	6.5 The Spurious 1.5 Sigma Shift	99
	6.6 Summary	100
Chapter 7	Excess Costs for One-Sided Specifications	101
	7.1 One-Sided Safety Specifications	101
	7.2 One-Sided Process Specifications	104
	7.3 One-Sided Product Specifications	108
	7.4 Excess Costs of Use for One-Sided Product Specifications	111
	7.5 Using One-Sided Product Specifications	114
	7.6 Reassessing the Run-Out Data	114
	7.7 The Contamination Data	116
	7.8 Summary	119
Chapter 8	Excess Costs for Targets at Boundaries	121
	8.1 The Excess Cost Function	121
	8.2 Using Tables Nine and Ten	123
	8.3 The Run-Out Data	124
	8.4 The Contamination Data	126
	8.5 Summary	128
Chapter 9	When Nominal Costs Change with Aim	129
	9.1 One-Sided Product Specifications without a Target	129
	9.2 One-Sided Product Specifications with a Target Value	136
	9.3 Target at Boundary	141
	9.4 Summary	144
Chapter 10	Excess Costs for Count Data	145
	10.1 Specifications and Count Data	145
	10.2 Effective Costs of Production for Counts of Items	147
	10.3 Effective Costs of Production for Counts of Events	148

PART THREE: TABLES OF EXCESS COSTS

Chapter 11	The Formulas for the Excess Costs	151
	11.1 The Structure of the Effective Cost of Production and Use	151
	11.2 The Average Costs of Scrap, Rework, and Use	152
	11.3 Finding the Effective Cost of Production and Use	157
	11.4 One-Sided Process Specifications	159
	11.5 The Excess Cost of Production with One-Sided Product Specs	160
	11.6 The Excess Cost of Use with One-Sided Product Specs	161
	11.7 One-Sided Product Specifications with Targets at Boundaries	162
Tables for Tw	o-Sided Specifications	169-216
Table One	When All Nonconforming Units Are Scrapped	170-176
Table Two	When All Nonconforming Units Are Reworked	178-184
Table Thre	When the Average Is on the Scrap Side of the Target Value and the Cost of Rework Is Equal to the Cost of Scrap	186-192
Table Four	When the Average Is on the Scrap Side of the Target Value and the Cost of Rework Is 0.1% the Cost of Scrap	194-200
Table Five	When the Average Is on the Rework Side of the Target Value and the Cost of Rework Is Equal to the Cost of Scrap	202-208
Table Six	When the Average Is on the Rework Side of the Target Value and the Cost of Rework Is 0.1% the Cost of Scrap	210-216
Tables for On	e-Sided Specifications	218-225
Table Seve	en Excess Costs of Scrap and Excess Costs of Use when Nonconforming Product Is Scrapped	218-221
Table Eigh	t Excess Costs of Rework and Excess Costs of Use when Nonconforming Product Is Reworked	222-225
Tables for On	e-Sided Specifications with Target at Boundary	226-240
Table Nine	When Nonconforming Product Is Scrapped	226-232
Table Ten	When Nonconforming Product Is Reworked	234-240

APPENDIX

I. Formulas for Measures of Dispersion		243
II. The Cov	verage of Three-Sigma Limits	244
III. The Transformation of Data		248
Table A.1	Bias Correction Factors for Measures of Dispersion	252
Table A.2	XmR Charts: Charts for Individual Values	254
Table A.3	Average and Range Charts Based on the Average Range	256
Table A.4	Average and Range Charts Based on the Median Range	258
Table A.5	Average and Standard Deviation Charts Based on the Average Standard Deviation Statistic	260
Table A.6	Average and Standard Deviation Charts Based on the Median Standard Deviation Statistic	262
Table A.7	Average and Root Mean Square Deviation Charts Based on the Average Root Mean Square Deviation Statistic	264
Table A.8	Average and Root Mean Square Deviation Charts Based on the Median Root Mean Square Deviation Statistic	266
Table A.9	Normal Theory Values of the Integrals IA, IB, IC, and ID	268
Table A.10	Burr and Normal Values for the Integrals IC and ID	277
Glossary of Symbols		283
Index		287