INFORMATION DISPLAY DIVISION

IDD MAINTENANCE AGREEMENT PROMOTION SERVICE PLAN 12/14/79 (CORRECTION)

Reference: Field Service Folder

(Corrections are underlined)

The IDD Maintenance Agreement Promotion Field Service Folder has a Tek part number which is orderable via normal channels <u>from Advertising</u>. When you order the folder, you should state the quantity and part number, <u>AX4186</u>. If you want the folders stuffed with the Stan Kouba letter, Field Service Program Brochure and Tek Field Office location sheets, state the word "Stuffed" after the part number of the folder.

--Jim Tiano 63-503 Ext. 3701

4054 POWER SWITCH MODIFICATION #M41675

There has been a modification to the 4054 which adds a solid state relay to the primary power circuitry. This is a reliability mod which will prevent the power switch from sticking in the on position.

The mod is Corporate Modification #M41675.

The part number of the mod kit is 045-0017-00. The kit is set up in CMS and is orderable from the field. Do not enter the order for the kit as a priority 1 or your order will be cancelled. The mod should be installed on all 4054's below serial number B011028.

This is a service update program, no charge to the customer. U.S. service will charge related expenses to activity code 18. International service will bill back related expenses as per the Subsidiary/Distribution installed product UPDATE procedures. The service update plan has been distributed.

--Frank Lees 63-503, ext. 3929