4052/4054 FOUR SLOT BACKPACK WITH A 4907 FILE MANAGER ROMPACK

When a 4907 File Manager Rompack is used with a 4052/4054 Four Slot Backpack the File Manager Rompack must be in the slot labeled 61.

The File Manager Rompack must be in the lowest addressable backpack slot. In a four slot backpack the order the slots are addressed are: 61, 71, 41, 51; the slot labeled 61 being the lowest and the slot labeled 51 being the highest.

In a two slot backpack the slot labeled 41 is the lowest addressable slot. In this case, the File Manager Rompack must be in the slot labeled 41.

--Frank Lees 63/503, ext. 3929 (W1)

4052/4054 VERSION 4.2 FIRMWARE

When updating a 4052 or 4054 to Version 4.2 the -02 Patch ROMs and FPLAs should be returned to Factory Service. The -01 or lower parts should <u>not</u> be returned, they cannot be reburned.

The procedure to return the -02 parts is explained in Wizard Workshop Article 10-13, 27 January 80, page 28.

--Frank Lees 63/503, ext. 3929