ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Report No: SR-2024-061

Facility: Northfield Sweaters Ltd.

Chemical storage is separated from the main building and fitted with secondary containment.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Emergency lighting, exit signage and the fire alarm panel were tested in the presence of factory management.

Assessment completed on: 27-Oct-2024

This assessment remains valid until: 27-Oct-2026

Signed: Rahim Uddin (synthetic)