ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Report No: SR-2025-908

Prepared for: Northfield Sweaters Ltd.

Chemical storage is separated from the main building and fitted with secondary containment.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Chemical storage is separated from the main building and fitted with secondary containment.

Chemical storage is separated from the main building and fitted with secondary containment.

Assessment completed on: 17/09/2025

This assessment remains valid until: 17/09/2027

Signed: Rahim Uddin (synthetic)