ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Assessment Ref: SR-2026-036

Facility: Northfield Sweaters Ltd.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Chemical storage is separated from the main building and fitted with secondary containment.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

Date of assessment: 19 April 2026

This assessment remains valid until: 18 April 2028

Signed: Nasrin Akter (synthetic)