ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Assessment Ref: SR-2024-443

Facility: Riverside Knitwear Ltd.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Chemical storage is separated from the main building and fitted with secondary containment.

Chemical storage is separated from the main building and fitted with secondary containment.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

Assessment completed on: 2024-03-06

Next assessment due by: 2026-03-06

Signed: Kamal Hossain (synthetic)