ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Report No: SR-2024-506

Facility: Green Thread Garments Ltd.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

Emergency lighting, exit signage and the fire alarm panel were tested in the presence of factory management.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

Chemical storage is separated from the main building and fitted with secondary containment.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Assessment completed on: 18-Dec-2024

This assessment remains valid until: 18-Dec-2026

Signed: Rahim Uddin (synthetic)