ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Report No: SR-2025-118

Facility: Sample Apparel Ltd.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Chemical storage is separated from the main building and fitted with secondary containment.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Load-bearing columns on floors 1 to 4 were checked for cracks; no new cracks were recorded since the last visit.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Assessment completed on: 01/03/2025

This assessment remains valid until: 01/03/2027

Signed: Rahim Uddin (synthetic)