PillarToPost Home Inspectors

Suite 200, 2501 Third Line, Oakville, ON L6H 7L4 | (905) 555-8844

HOME INSPECTION REPORT

Report #: PTP-OAK-2025-00463

Inspection Date:	March 4, 2025 | Time: 9:00 AM - 1:00 PM (4 hrs)
Property Address:	27 Chartwell Crescent, Oakville, ON L6J 3Z8
Client:	Bob Thomas Johnson & Alice Marie Johnson
Inspector:	Robert K. Fitzgerald | Lic #: ON-RHI-09421
Weather Conditions:	Overcast, -2C, dry conditions, no snow

OVERALL ASSESSMENT: **FAIR CONDITION -- Multiple Items Require Attention**

This 33-year-old detached home shows signs of deferred maintenance. Several systems are original and approaching or past typical service life. Foundation and HVAC concerns warrant attention.

1. ROOF & ATTIC

Roof Covering — SATISFACTORY

Roof in good condition, adequate useful life remaining.

Gutters & Downspouts — SATISFACTORY

Properly pitched, no leaks observed.

Attic Insulation — SATISFACTORY

Adequate insulation levels for climate zone.

2. EXTERIOR

Foundation (Visible) — MONITOR

Hairline cracks observed on east wall. Recommend structural engineer assessment.

Exterior Cladding — SATISFACTORY

Cladding in good condition overall.

Windows & Doors — MONITOR

3 of 14 window seals broken, condensation between panes.

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.

SYNTHETIC DOCUMENT -- FOR DEMONSTRATION PURPOSES ONLY

3. INTERIOR -- STRUCTURE & FINISHES

Floors — GOOD

Flooring in good condition throughout.

Walls & Ceilings — SATISFACTORY

Painted drywall, minor cosmetic items only.

Doors (Interior) — GOOD

All doors latch and operate properly.

4. PLUMBING

Water Supply Lines — SATISFACTORY

Water pressure tested -- normal range. No evidence of leaks.

Drain, Waste & Vent — SATISFACTORY

All fixtures drain freely.

Hot Water Tank — SATISFACTORY

Hot water system functional.

5. HEATING & COOLING

Furnace / HVAC — MONITOR

HVAC system original 1992 (33 years old). Functional but approaching end of useful life. Replacement recommended within 2-3 years.

Ductwork & Registers — SATISFACTORY

Ductwork in good condition.

6. ELECTRICAL

Electrical Panel — SATISFACTORY

Panel in good condition, properly labelled.

GFCI Protection — SATISFACTORY

GFCI outlets present and tested in all required locations.

Smoke & CO Detectors — SATISFACTORY

All detectors tested and operational.

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.

SYNTHETIC DOCUMENT -- FOR DEMONSTRATION PURPOSES ONLY

7. KITCHEN & BATHROOMS

Kitchen — SATISFACTORY

Kitchen functional, some cabinet hardware loose.

Bathrooms — MONITOR

Some grout cracking in bathroom. Balcony sliding door track needs cleaning.

8. SUMMARY OF FINDINGS

IMMEDIATE ACTION REQUIRED (1)

* Foundation hairline cracks observed on east wall -- recommend structural engineer assessment (~$500 consultation)

MONITOR / BUDGET FOR FUTURE (3 item(s))

* HVAC system original 1992 -- replacement recommended within 2-3 years (~$8,000-$12,000)
* Several window seals broken (3 of 14 windows) -- condensation between panes, budget for replacement (~$3,000-$5,000)
* Roof approximately 15 years old -- approaching end of useful life, budget for replacement within 3-5 years (~$12,000-$18,000)

MAINTENANCE NOTES (3 item(s))

* Eavestroughs need cleaning and re-pitching on north side
* Exterior wood trim showing paint peeling -- repaint recommended within 12 months
* Basement sump pump should be tested quarterly -- currently functional

INSPECTOR DECLARATION

I, Robert K. Fitzgerald, Certified Home Inspector, confirm that this report was prepared following the Standards of Practice of CAHPI and represents my professional opinion based on conditions observed on the inspection date only. This report does not constitute a warranty or guarantee of any systems or components.

Robert K. Fitzgerald Lic #ON-RHI-09421 | Date: March 4, 2025