Inspection Date:	March 1, 2025	Time: 9:00 AM – 12:30 PM (3.5 hrs)
Property Address:	4718 Coronation Drive SW, Calgary, AB T3E 4Y2
Client:	Marcus Alejandro Delgado & Sofia Renata Delgado
Inspector:	Derek W. Oliphant, CAHPI Certified	Lic #: AB-CI-04472
Weather Conditions:	Partly cloudy, -4°C, light snow, dry ground, no precipitation during inspection
Property Occupancy:	Occupied by sellers — furnished. All systems accessible.

OVERALL ASSESSMENT: **GOOD CONDITION — Minor Items Noted**

This property is in good overall condition for its age (17 years). No major structural, safety, or mechanical deficiencies were identified.

1. ROOF & ATTIC

Roof Covering — SATISFACTORY
Asphalt shingles, approximately 8–10 years old, 60–70% estimated useful life remaining. No or missing damaged shingles observed.

Gutters & Downspouts — SATISFACTORY
Aluminum gutters in good condition, properly pitched, downspouts discharge away from foundation.

Attic Insulation & Ventilation — SATISFACTORY
R-40 blown cellulose insulation. Ridge and soffit vents functional. No evidence of moisture or pest intrusion.

Roof Flashings — GOOD
Step, counter, and chimney flashings sealed and in good condition.

2. EXTERIOR

Foundation (Visible) — SATISFACTORY
Poured concrete foundation. No significant cracks or efflorescence observed at visible portions. Grading slopes away from foundation.

Exterior Cladding — SATISFACTORY
Vinyl siding in good condition. Some minor fading on south-facing elevation — cosmetic only.

Windows & Doors (Exterior) — SATISFACTORY
Double-glazed vinyl windows throughout. Weatherstripping in good condition. No failed seals observed.

Driveway & Walkways — MONITOR
Concrete driveway shows minor cracking at expansion joint — monitor annually, seal when occurs. widening

Garage (Double Attached) — GOOD
Concrete floor in good condition. Auto-reverse safety function on door openers confirmed operational.

3. INTERIOR — STRUCTURE & FINISHES

Floors — GOOD
Engineered hardwood main level, carpet upper level, ceramic tile bathrooms and laundry — all in good condition.

Walls & Ceilings — SATISFACTORY
Painted drywall throughout. Minor nail pops in upper hallway ceiling — cosmetic, common for age of home.

Staircase & Railings — SATISFACTORY
Solid hardwood staircase. Handrail secure. Balusters at code-required spacing.

Windows (Interior) — SATISFACTORY
All windows operate freely. Locks functional. Window wells on basement egress windows clear.

Doors (Interior) — GOOD
All interior doors latch and operate properly. Fire-rated door between garage and house confirmed.

Basement — SATISFACTORY
Fully developed basement — bedroom, 3-piece bath, rec room. No evidence of moisture intrusion or efflorescence.

4. ROOFING, INSULATION & VAPOUR BARRIER

Exterior Walls Insulation — SATISFACTORY
R-22 estimated batt insulation in walls — adequate for Alberta climate code at time of construction.

Vapour Barrier — N/A
Not directly accessible. No evidence of moisture issues at interior surfaces to suggest vapour barrier deficiency.

5. PLUMBING

Water Supply Lines — SATISFACTORY
Copper supply lines throughout. Water pressure tested at 65 PSI — normal. No evidence of leaks.

Drain, Waste & Vent — SATISFACTORY
ABS plastic drain lines. All fixtures drain freely. No slow drains. Venting appears adequate.

Hot Water Tank — MONITOR
Natural gas power vent hot water tank, 50 US gal. Age: approximately 9 years. Functional but end nearing of typical 10–12 yr lifespan. Plan for replacement within 1–3 years.

Fixtures & Faucets — SATISFACTORY
All faucets, toilets, and shower/tub fixtures function properly. No visible leaks under sinks.

Laundry Connections — GOOD
Proper vented standpipe, hot/cold connections. Floor drain present. Condensing dryer vented per code.

6. HEATING & COOLING

Furnace — GOOD
Lennox high-efficiency (95% AFUE) natural gas furnace. Age: 6 years. Serviced annually per and service stickers. Flame heat exchanger visually inspected — no visible cracks.

Air Conditioning — GOOD
Central A/C unit (Lennox, matched to furnace). Age: 6 years. Not operated (below 15°C) but no visible deficiencies noted.

HRV / Ventilation — SATISFACTORY
Heat Recovery Ventilator present and operational. Filters show recent servicing.

Ductwork & Registers — SATISFACTORY
Sheet metal ductwork in good condition. All rooms have supply and return air registers. Balanced flow confirmed.

Gas Piping — SATISFACTORY
Black steel gas supply piping, properly supported. No CO detector odour or indications of leak.

7. ELECTRICAL

Electrical Panel — SATISFACTORY
200A main panel, breaker type. No double-tapped breakers, corrosion, or scorch marks. Panel labelling complete.

Wiring (Visible) — SATISFACTORY
Copper wiring throughout. Grounded 3-prong outlets. AFCI breakers on bedroom circuits per code. current

GFCI Protection — SATISFACTORY
GFCI outlets present and tested in all bathrooms, kitchen counters, garage, and exterior locations.

Smoke & CO Detectors — SATISFACTORY
Smoke detectors on each floor and in each bedroom. CO detector adjacent to furnace room. All — tested operational.

Exterior Outlets & Lighting — GOOD
Weather-protected exterior outlets at front and back. Motion-sensing light at garage. All functional.

8. KITCHEN & BATHROOMS

Kitchen — GOOD
Updated kitchen (approx. 4 years ago). Quartz counters, SS appliances. Exhaust fan vented to No exterior. evidence of water damage under sink.

Main Bathroom (Upper) — SATISFACTORY
4-piece. Grout and caulking in good condition. No evidence of moisture behind tile. Exhaust fan functional.

Ensuite (Upper) — SATISFACTORY
5-piece ensuite. Walk-in shower with glass enclosure, in-floor heat. Grout/caulking sound. Exhaust fan operational.

Powder Room (Main) — GOOD
2-piece, updated vanity. All functional.

Basement Bathroom — SATISFACTORY
3-piece. Shower stall with tile surround, sound grout and caulk. No evidence of moisture.

9. SUMMARY OF FINDINGS

IMMEDIATE ACTION REQUIRED (None)

- None identified

SAFETY ITEMS (None)

- None identified

REPAIRS RECOMMENDED (1 item(s))

- None identified

MONITOR / BUDGET FOR FUTURE (2 item(s))

- Hot water tank (age ~9 yrs) — budget for replacement within 1–3 years (~$1,200–$1,600 installed)
- Concrete driveway hairline crack at expansion joint — monitor, seal if widening

MAINTENANCE NOTES (3 item(s))

- Attic insulation and ventilation reviewed — no action required at this time
- Annual HVAC servicing recommended (furnace/AC) — currently up to date
- Recommend caulking perimeter of exterior windows during warm weather (cosmetic seal maintenance)

INSPECTOR DECLARATION

I, Derek W. Oliphant, CAHPI Certified Home Inspector, confirm that this report was prepared following the Standards of Practice of CAHPI and represents my professional opinion based on conditions observed on the inspection date only. This report does not constitute a warranty or guarantee of any systems or components.

Derek W. Oliphant CAHPI Lic #AB-CI-04472 | Date: March 1, 2025

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.
SYNTHETIC DOCUMENT — FOR DEMONSTRATION PURPOSES ONLY | PillarToPost Home Inspectors