Oakwood Residential Build — Lot 14

Date: 2026-03-21
Location: 123 Oakwood Drive, Austin TX 78701
Weather: Sunny, 72°F, light wind
Prepared by: J. Rivera

SUMMARY

Framing on the south and west walls is complete. Rough-in plumbing is underway beneath the slab. One tripping hazard identified near the main stairwell.

WORK COMPLETED

- South wall: framing (completed)
- West wall: framing (completed)
- Window and door rough openings cut (completed)
- Temporary bracing installed (completed)

PROGRESS UPDATE

Project is on schedule. Roof sheathing is expected to begin Monday.

ISSUES / DELAYS

- Lumber delivery for second floor delayed — Impact: Second-floor framing pushed back 2 days [medium]

SAFETY NOTES

- Debris pile near stairwell entry — tripping hazard — Action required: Clear debris before end of day
- Hard hat and hi-vis vest required in all active zones — Action required: Enforce PPE compliance at site entry

NEXT STEPS

- Clear debris from stairwell area (high)
- Complete rough-in plumbing under slab (high)
- Begin second-floor framing once lumber arrives (medium)

RESOURCES

CREW

6-person framing crew, 2 plumbers on site

EQUIPMENT

- Nail gun
- Scaffolding
- Concrete saw

MATERIALS

- 2x6 lumber
- OSB sheathing
- PVC pipe
- Concrete mix

ADDITIONAL NOTES

Owner walked the site at 2pm and approved framing layout.

PHOTO DOCUMENTATION

PROGRESS

Framing for the exterior walls is in progress.

- A ladder is positioned on the left side of the room.
- The floor appears to be wet.
- A person is standing inside the framed structure.

PROGRESS

Plumbing rough-in work is in progress under the slab.

- White PVC pipes are laid out on the ground.
- Wooden forms are set up around the perimeter.
- Gravel is laid down in certain areas.

GENERAL

Scattered debris and lumber are present near a construction site.

- The area contains scattered pieces of lumber and debris.
- A shovel is leaning against a wooden structure.
- The ground appears to be dirt or mud.

ISSUE

The wall above the door has significant cracks and damage.

- The wall has large cracks and crumbling plaster.
- The damage is located above a door frame.
- The wall's surface is partially peeled and exposed.