

PRODUCT OBSOLESCENCE NOTICE

August 4, 2011

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are becoming obsolete with immediate effect:

Model Number	Recommended alternative
ULQ-1.2/15-D48N	No replacement available
ULQ-1.2/15-D48N-C	No replacement available
ULQ-1.2/15-D48NM	No replacement available
ULQ-1.2/15-D48NM-C	No replacement available
ULQ-1.2/15-D48P	No replacement available
ULQ-1.2/15-D48P-C	No replacement available
ULQ-1.2/15-D48PM	No replacement available
ULQ-1.2/15-D48PM-C	No replacement available
ULQ-1.2/25-D24N	No replacement available
ULQ-1.2/25-D24N-C	No replacement available
ULQ-1.2/25-D24NM	No replacement available
ULQ-1.2/25-D24NM-C	No replacement available
ULQ-1.2/25-D24P	No replacement available
ULQ-1.2/25-D24P-C	No replacement available
ULQ-1.2/25-D24PM	No replacement available
ULQ-1.2/25-D24PM-C	No replacement available
ULQ-1.2/25-D48N	UCQ-1.2/30-D48N-C
ULQ-1.2/25-D48N-C	UCQ-1.2/30-D48N-C
ULQ-1.2/25-D48NM	No replacement available
ULQ-1.2/25-D48NM-C	No replacement available
ULQ-1.2/25-D48P	UCQ-1.2/30-D48P-C
ULQ-1.2/25-D48P-C	UCQ-1.2/30-D48P-C
ULQ-1.2/25-D48PM	No replacement available
ULQ-1.2/25-D48PM-C	No replacement available
ULQ-1.5/15-D48N-C	UCQ-1.5/25-D48N-C
ULQ-1.5/15-D48NM	No replacement available
ULQ-1.5/15-D48NM-C	No replacement available
ULQ-1.5/15-D48P-C	UCQ-1.5/25-D48P-C
ULQ-1.5/15-D48PM	No replacement available
ULQ-1.5/15-D48PM-C	No replacement available
ULQ-1.5/25-D24N-C	No replacement available
ULQ-1.5/25-D24NM	No replacement available
ULQ-1.5/25-D24NM-C	No replacement available
ULQ-1.5/25-D24P-C	No replacement available
ULQ-1.5/25-D24PM	No replacement available
ULQ-1.5/25-D24PM-C	No replacement available
ULQ-1.5/25-D48N-C	UCQ-1.5/25-D48N-C



Model Number	Recommended alternative
ULQ-1.5/25-D48NM	No replacement available
ULQ-1.5/25-D48NM-C	No replacement available
ULQ-1.5/25-D48P-C	UCQ-1.5/25-D48P-C
ULQ-1.5/25-D48PM	No replacement available
ULQ-1.5/25-D48PM-C	No replacement available
ULQ-1.8/15-D24N	No replacement available
ULQ-1.8/15-D48N-C	UCQ-1.8/30-D48N-C
ULQ-1.8/15-D48NL2-C	UCQ-1.8/30-D48N-C
ULQ-1.8/15-D48NM	No replacement available
ULQ-1.8/15-D48NM-C	No replacement available
ULQ-1.8/15-D48P	UCQ-1.8/30-D48P-C
ULQ-1.8/15-D48P-C	UCQ-1.8/30-D48P-C
ULQ-1.8/15-D48PM	No replacement available
ULQ-1.8/15-D48PM-C	No replacement available
ULQ-1.8/25-D24N-C	No replacement available
ULQ-1.8/25-D24NM	No replacement available
ULQ-1.8/25-D24NM-C	No replacement available
ULQ-1.8/25-D24P	No replacement available
ULQ-1.8/25-D24P-C	No replacement available
ULQ-1.8/25-D24PM	No replacement available
ULQ-1.8/25-D24PM-C	No replacement available
ULQ-1.8/25-D48N-C	UCQ-1.8/30-D48N-C
ULQ-1.8/25-D48NM	No replacement available
ULQ-1.8/25-D48P-C	UCQ-1.8/30-D48P-C
ULQ-1.8/25-D48PM	No replacement available
ULQ-1.8/25-D48PM-C	No replacement available
ULQ-1/25-D24N	No replacement available
ULQ-1/25-D24N-C	No replacement available
ULQ-1/25-D24NM	No replacement available
ULQ-1/25-D24NM-C	No replacement available
ULQ-1/25-D24P	No replacement available
ULQ-1/25-D24P-C	No replacement available
ULQ-1/25-D24PM	No replacement available
ULQ-1/25-D24PM-C	No replacement available
ULQ-1/25-D48N	No replacement available
ULQ-1/25-D48N-C	No replacement available
ULQ-1/25-D48NM	No replacement available
ULQ-1/25-D48NM-C	No replacement available
ULQ-1/25-D48P	No replacement available
ULQ-1/25-D48P-C	No replacement available
ULQ-1/25-D48PM	No replacement available
ULQ-1/25-D48PM-C	No replacement available
ULQ-2.5/15-D48N-C	UCQ-2.5/30-D48N-C
ULQ-2.5/15-D48NL1-C	UCQ-2.5/30-D48N-C
ULQ-2.5/15-D48NM-C	No replacement available
ULQ-2.5/15-D48P-C	UCQ-2.5/30-D48P-C



Model Number	Recommended alternative
ULQ-2.5/15-D48PM-C	No replacement available
ULQ-2.5/20-D24N-C	No replacement available
ULQ-2.5/20-D24NM-C	No replacement available
ULQ-2.5/20-D24P-C	No replacement available
ULQ-2.5/20-D24PM	No replacement available
ULQ-2.5/20-D24PM-C	No replacement available
ULQ-2.5/20-D48N-C	UCQ-2.5/30-D48N-C
ULQ-2.5/20-D48NL2-C	UCQ-2.5/30-D48N-C
ULQ-2.5/20-D48NM-C	No replacement available
ULQ-2.5/20-D48P-C	UCQ-2.5/30-D48P-C
ULQ-2.5/20-D48PM-C	No replacement available
ULQ-2/15-D48N	No replacement available
ULQ-2/15-D48N-C	No replacement available
ULQ-2/15-D48NM	No replacement available
ULQ-2/15-D48NM-C	No replacement available
ULQ-2/15-D48P	No replacement available
ULQ-2/15-D48P-C	No replacement available
ULQ-2/15-D48PM	No replacement available
ULQ-2/15-D48PM-C	No replacement available
ULQ-2/25-D24N	No replacement available
ULQ-2/25-D24N-C	No replacement available
ULQ-2/25-D24NM	No replacement available
ULQ-2/25-D24NM-C	No replacement available
ULQ-2/25-D24P	No replacement available
ULQ-2/25-D24P-C	No replacement available
ULQ-2/25-D24PM	No replacement available
ULQ-2/25-D24PM-C	No replacement available
ULQ-2/25-D48N-C	No replacement available
ULQ-2/25-D48NM	No replacement available
ULQ-2/25-D48NM-C	No replacement available
ULQ-2/25-D48P	No replacement available
ULQ-2/25-D48P-C	No replacement available
ULQ-2/25-D48PM	No replacement available
ULQ-2/25-D48PM-C	No replacement available
ULQ-3.3/20-D24NM	ULQ-3.3/20-D24NM-C
ULQ-5/15-D24PM	ULQ-5/15-D24PM-C
ULQ-5/15-D48NM	ULQ-5/15-D48NM-C

Via this notice we are offering our existing customers for these products the opportunity for a last time or lifetime buy (LTB) and we will accept orders until 10/31/11. Please note that this LTB will be subject to a minimum order quantity of 210 pcs. unless product is available from stock. Multiple releases will be accepted with a constraint that no releases may be scheduled past a ship date of 4/30/12. Pricing for these products will be granted through the SPR (Special Price Request) process only. Once placed, LTB orders cannot be cancelled, rescheduled, or



returned for any reason other than product quality. Quality issues need to be identified and communicated within 30 days of shipment.

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at http://www.murata-ps.com/offices.html.

