

PRODUCT OBSOLESCENCE NOTICE

27 September 2010

Dear Valued Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are now obsolete. Under normal product life management MPS would offer a Last-Time-Buy (LTB) opportunity to all customers; unfortunately we cannot offer a LTB for this series of products due to the obsolescence of a critical component by one of our suppliers. MPS plans to support current orders that have been placed on the factory with our remaining raw materials inventory. The only remaining finished goods inventory for the below part numbers is either in MPS finished goods inventory or with our franchised distributors.

Product Part Number	Recommended Alternative
HL01R05D15ZC	No Recommendation
HL01R05S05YC	No Recommendation
HL01R05S05ZC	No Recommendation
HL01R05S12YC	No Recommendation
HL01R24D05ZC	No Recommendation
HL01R24D12YC	No Recommendation
HL01R24D15YC	No Recommendation
HL01R24S05YC	No Recommendation

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at http://www.murata-ps.com/offices.html.