


Anodizing Instruction Notes

Please minimize marks from Anodizing/ Anodizing Hanging


Please use minimum number of contact points to minimize mark

Please make marks as small as possible

Please do not hang multiple parts



Please make marks as small as possible



All surface polish to < Ra 1.6

All inner radius clean
and smooth

All surfaces must be clean, shiny and smooth to the touch

All inner radius clean
and smooth