CN7	CN10	MCU Pin #	PINs	FUNCTIONS	LABELs	Notes
1			PC10	UART4_TX/SPI3_SCK		
2		52	PC11	UART4_RX/SPI3_MISO		
3			PC12	SPI3_MOSI		
4		54	PD2			Unused
5			VDD			
6			E5V			
7 8		60	BOOT0 GND			
9			N.C.			No Connect
10			N.C.			No Connect
11			N.C.			No Connect
12			+3.3V			
13		46	PA13*	SYS_JTMS-SWDIO	TMS	
14			RESET			
15			PA14*	SYS_JTCK-SWCLK	TCK	
16			+3.3V			l lava and
17 18		50	PA15 +5V			Unused
19			GND			
20			GND			
21		59	PB7	GPIO_Output	LCD_D7	
22			GND		_	
23		2	PC13	GPIO_EXTI13	B1 [Blue PushButton]	
24			VIN			
25			PC14-OSC32_IN*	RCC_OSC32_IN		N- C
26			N.C.	DCC OCC32 OUT		No Connect
27 28			PC15-OSC32_OUT* PA0	RCC_OSC32_OUT GPIO Output	MOTOR1 DIR1	
29			PF0-OSC_IN	RCC OSC IN	MOTORI_DIKI	
30			PA1	GPIO Output	MOTOR1 DIR2	
31			PF1-OSC OUT	RCC OSC OUT		
32			PA4	DAC1_OUT1	STEP_VREF	
33			VBAT			
34			PB0			Unused
35			PC2	ADC1_IN8	ADC_3	
36			PC1	ADC1_IN7	ADC_2	
37 38			PC3 PC0	GPIO_Output ADC1 IN6	STEP_RST ADC_1	
30	1		PC9	GPIO Input	STEP_MONI	
	2		PC8	GPIO Output	STEP PS	
	3	61	PB8	I2C1_SCL	_	
	4		PC6			
	5		PB9	I2C1_SDA		
	6		PC5	GPIO_Output	STEP_DIR	
	7 8	12	AVDD U5V			
	9		GND			
	10		N.C.			No Connect
	11		PA5	GPIO_Output	LD2 [Green Led]	
	12	45	PA12	TIM4_CH2	MOTOR2_B	
	13		PA6	TIM3_CH1	MOTOR1_A	
	14		PA11	TIM4_CH1	MOTOR2_A	
	15		PA7	TIM3_CH2	MOTOR1_B	
	16 17		PB12 PB6	GPIO_Output GPIO Output	LCD_E LCD_D6	
	18		PB11	GPIO_Output	MOTOR2 DIR2	
	19		PC7	o_output		
	20		GND			
	21		PA9	TIM1_CH2	DC_MOTOR_PWM2	
	22		PB2			Unused
	23		PA8	TIM1_CH1	DC_MOTOR_PWM1	11
	24 25		PB1	CDIO Output	MOTOD2 DID1	Unused
	25 26		PB10 PB15	GPIO_Output GPIO Output	MOTOR2_DIR1 LCD_RW	
	20		PB4	GPIO_Output	LCD_RW LCD_D4	
	28		PB14	TIM15 CH1	STEP	
	29		PB5	GPIO_Output	LCD_D5	
	30	34	PB13	GPIO_Output	LCD_RS	
	31		PB3*	SYS_JTDO-TRACESWO	SWO	
	32		AGND			
	33		PA10	TIM1_CH3	LCD_BKLT	
	34 35		PC4 PA2	GPIO_Output USART2 TX	STEP_OE USART TX	
	36		N.C.	USARIZ_IA	USARI_IX	No Connect
	37		PA3	USART2 RX	USART RX	. TO COMMENT
	38		N.C.			No Connect