

Assembly Drawing

Top-side placement is provided in fabrication/pick_and_place.csv.

Verify connector orientation before assembly.