

Current Service Bulletins

Version 1.0 — Internal Use

1. Firmware Sync Advisory

Some units running older firmware builds have shown intermittent lag in module communication. The fix is simple. Update to the latest package and restart the system once the sync completes. If the issue persists, clear temporary configuration files through the maintenance menu and allow the device to rebuild its internal cache during the next boot.

2. Power Module Connector Notice

A few installations reported slight loosening of the main power connector after extended vibration exposure. The revised locking latch improves grip. During the next service cycle, inspect the connector, reseal it firmly, and apply the updated latch if your unit predates the revision. There's no safety risk, but stable power delivery improves overall performance.

3. Sensor Drift Calibration Alert

In some environments with large temperature swings, certain sensors may drift from their baseline. A calibration patch is available and should be applied during routine maintenance. Once installed, run the auto-calibration utility so the module can realign its reference points. Units already updated this quarter are unaffected.

4. Cooling Path Obstruction Reminder

A batch of field reports shows dust buildup restricting airflow around the cooling channel. This tends to show up in setups placed near fabric surfaces or enclosed spaces. Add a quick visual inspection to your next visit. Clear any debris and make sure the airflow path stays unobstructed to avoid thermal throttling.

5. Accessory Mount Revision

The mounting arm for one of the optional accessories has a revised torque spec. Earlier guidance had a higher rating than necessary, which could stress the bracket over time. Follow the new torque level provided in the accessory guide. Existing mounts don't require replacement unless physical stress marks are visible.

6. Software Logging Patch

A minor issue in the diagnostic logging module caused repeated entries in long-running sessions. The new patch reduces redundant logs and improves clarity during post-analysis. Apply it whenever you update the main software package. No manual cleanup is needed; the patch handles it automatically.

7. Start-Up Delay Case

A small number of users noticed a delay during boot after prolonged inactivity. The cause is a stale initialization file. A reset script is now included in the latest maintenance build. Once applied, start-up times return to normal. This doesn't affect any stored data or custom configurations.

8. Updated Safety Cut-Off Logic

The automatic cut-off system received a logic improvement that handles borderline cases more gracefully. It's a performance tweak rather than a fix, but updating ensures consistent behavior across all deployments. No configuration changes required after applying it.