M. Romero Roofing

COMMERCIAL · RESIDENTIAL · SINCE 1976 | Licensed & Insured CCC 044016

5280 NW 77th Court, Doral, FL 33166
Ph 305-388-3704 · Fax 305-805-8488
www.mromeroroofing.com

Roof Inspection Report

PROPERTY INSPECTED **6550 SW 27th Street**	**DATE OF INSPECTION** **10/14/2026**
TYPE OF INSPECTION **Insurance**	**REPORT VALID** **30 days from 10/14/2026 (through 11/13/2026)**
INSPECTOR **Marc Romero**	**INSPECTION FEE** **$225.00 (no additional charges)**

Roof Summary

ROOF TYPE	APPROX. AGE	EST. REMAINING LIFE	OVERALL CONDITION
Built-up roof (B.U.R.), hot mop	**10 years**	**5 years**	**Fair**

Condition by Component

Component	Rating	Inspector comments
General condition of roof	**Fair**	
Gravel stop	**N/A**	
Drip edge	**Fair**	
Valley metal	**N/A**	
Flashings	**Fair**	
Parapet wall	**Poor**	Parapet wall flashing needs to be sealed. Exposed fasteners.
Fascia board and soffit	**Needs Replacement**	Visible termite damage.
Sheathing and rafters, exposed ceilings (carport only)	**Fair**	Visible wood rot at the deck at the carport.
Sheathing and rafters, above ceilings	**N/A**	No attic space.
Leak marks on interior plaster	—	No stains currently visible.

General comments: Visible leak repairs at the existing roof (total of 3).

5280 NW 77th Court, Doral, FL 33166
Ph 305-388-3704 · Fax 305-805-8488
www.mromeroroofing.com

Findings and Photos

1. Roof Overview ● Fair

Built-up hot-mop roof, approximately 10 years old, with an estimated 5 years of remaining service life. Overall condition rated Fair.



Photo 5. Field of the flat roof with pipe penetrations.

2. Parapet Wall ● Poor

The parapet wall flashing needs to be sealed, and there are exposed fasteners along the wall.



Photo 2. Parapet wall flashing with exposed fasteners.



Photo 3. Parapet wall flashing and its base at the lower roof.

5280 NW 77th Court, Doral, FL 33166
Ph 305-388-3704 · Fax 305-805-8488
www.mromeroroofing.com

3. Fascia Board and Soffit ● Needs Replacement

Visible termite damage to the fascia board. Fascia board and soffit need replacement.



Photo 9. Fascia corner with damaged and separated wood.



Photo 1. Front eave fascia and soffit.



Photo 10. Rear eave fascia and drip edge.

4. Previous Leak Repairs ● Noted

Three visible leak repairs were found on the existing roof.



Photo 6. Leak repair 1.



Photo 7. Leak repair 2, next to a pipe penetration.



Photo 8. Leak repair 3, at the roof edge.

5. Carport Deck

Sheathing and rafters are exposed only at the carport and were rated Fair. Visible wood rot at the deck. No attic space, so sheathing and rafters above the interior ceilings could not be inspected. No leak stains are currently visible on the interior plaster.

5280 NW 77th Court, Doral, FL 33166
Ph 305-388-3704 · Fax 305-805-8488
www.mromeroroofing.com

Terms of This Report

This is a roof inspection report. It is NOT A GUARANTEE. This report is valid for thirty (30) days from the date of inspection, 10/14/2026.

This is a report made to the best of our ability on the existing conditions of the roof coverings. As all areas of the roof and attic are not accessible or visible and the roofing membranes are not visible due to coverings such as tile, gravel, and other coatings, the contractor cannot guarantee against any hidden defects, future leaks or repairs. No inspection has been made for such structural defects as would require engineering skill and practices.

Inspector	Date
Marc Romero	**10/14/2026**
M. Romero Roofing · CCC 044016	