

Invoice

Invoice no. MW-26-04-1107
Invoice date 08 April 2026
Payment due by 22 April 2026

Sink reconnection and temporary worktops (urgent remedial works)

Bill to
Neil Whitlock
82 Roundhay Avenue
Leeds LS8 1QU
07931 442 117Job site (same)
82 Roundhay Avenue
Leeds LS8 1QU
Attended: 08 April 2026, Wed call-out
Engineer: Owen Marsden (Director)

Summary of work carried out

Customer's kitchen had been left part-completed by a previous contractor: the kitchen sink had been disconnected and there were no fitted worktops on the base units. With small children in the household, the customer asked us to carry out the minimum work necessary to make the kitchen safe and usable. Attended on 08 April 2026. Reconnected the sink with new isolation valves and a fresh waste trap; supplied and fitted temporary plywood worktops across the 4.5m run with sealed edges; isolated the unfinished kitchen ring at the consumer unit pending a qualified second-fix.

Description	Hours	Rate	Amount
Call-out fee (within 48 hours, weekday)	-	Fixed	£60.00
Reconnect kitchen sink: hot and cold feeds, two 15 mm isolation valves, waste trap, pressure test	2.50	£80.00	£200.00
Supply and fit temporary plywood worktops (4.5 m run, edges sealed, openings cut for sink and hob)	3.00	£75.00	£225.00
Materials: 18 mm WBP plywood (4.5 m run), edge banding, sealant, screws	-	-	£85.00
Materials: 15 mm isolation valves x2, waste trap, PTFE tape, compression olives	-	-	£36.67
Make-safe of exposed kitchen ring at consumer unit and labelling (safety only - not certified second-fix)	0.75	£80.00	£60.00
Subtotal (ex VAT)			£666.67
VAT @ 20%			£133.33
Total payable (inc. VAT)			£800.00

How to pay

Account name: MarsdenWell Plumbing & Heating Ltd
Sort code: 30-92-04 Account no.: 81223145
Reference: MW-26-04-1107
Cards accepted by phone on 0113 244 0098. Payment terms: 14 days from invoice date.

Note. This invoice covers urgent remedial works only (sink reconnection and temporary worktops) so that the kitchen can be safely used in the short term. It does not constitute a completed second-fix and the kitchen electrical installation has not been certified as fit for re-energising. A separate NICEIC inspection, second-fix and permanent worktop installation will still be required.