

Mobil™

Unit ID: 4-PHU-2

Asset ID: 50326105

Description: Hyd pump

Account Information

Sample Information

Equipment Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample ID: 25308253045

Service Level: Essential

Bottle ID: a003623808

Tested Lubricant: QUAKER QUINTOLUBRIC 888-46

Asset Class: Hydraulic

Manufacturer:

Model:

Lubricant: QUAKER QUINTOLUBRIC 888-46

Sample Data & Trends

Sample Info	Report Status	Caution	Alert	Alert	Alert	Alert
	Sample ID	24205983055	24205472055	24330410036	25147349010	25308253045
	Service Level	Enhanced	Essential	Essential	Essential	Essential
	Bottle ID	b046769977	a030135884	a033582868	a033684080	a003623808
	Tested Lubricant	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46
	Sampled	16 Jul 2024	16 Jul 2024	13 Nov 2024	18 May 2025	17 Jul 2025
	Reported	26 Jul 2024	29 Jul 2024	27 Nov 2024	29 May 2025	06 Nov 2025
	Equipment Age					
	Oil Age					
	Make-up Volume					
	Oil Changed	Yes	Yes			
	Filter Changed					
Lubricant	Contamination Rating	Caution	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Alert	Alert	Alert	Alert
	Lubricant Rating	Normal	Caution	Alert	Alert	Alert
	Visc@40C (cSt)		54.7	61.3	60.1	63.4
	TAN (mg KOH/g)		2.28	1.68	1.60	1.64
Wear (ppm)	Water (Hot Plate)		NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)		0	0	0	0
	Al (Aluminum)		1	0	0	0
	Cr (Chromium)		1	1	1	1
	Cu (Copper)		2	2	5	1
	Fe (Iron)		165	79	56	66
	Mo (Molybdenum)		0	0	0	0
	Ni (Nickel)		0	0	0	0
	Pb (Lead)		2	1	2	1
Contaminant (ppm)	Sn (Tin)		314	325	315	333
	K (Potassium)		1	2	1	0
	Na (Sodium)		3	3	3	3
	Si (Silicon)		4	3	2	3
Additive (ppm)	B (Boron)		0	1	4	2
	Ba (Barium)		0	0	0	0
	Ca (Calcium)		36	15	14	12
	Mg (Magnesium)		1	0	0	0
	P (Phosphorus)		118	117	108	125
	Zn (Zinc)		25	8	12	7

Viscosity

Date	Visc@40C (cSt)
16 Jul 2024	0
16 Jul 2024	55
13 Nov 2024	62
18 May 2025	60
17 Jul 2025	63

Wear

Date	Ag (Silver)	Al (Aluminum)	Cr (Chromium)	Cu (Copper)	Fe (Iron)	Ni (Nickel)	Pb (Lead)	Sn (Tin)
16 Jul 2024	0	1	1	2	165	0	2	314
16 Jul 2024	0	0	1	2	79	0	1	325
13 Nov 2024	0	0	1	5	56	0	2	315
18 May 2025	0	0	1	1	66	0	1	333
17 Jul 2025	0	0	1	1	66	0	1	333

Contaminants

Date	Na (Sodium)	K (Potassium)	Si (Silicon)
16 Jul 2024	0	1	0
16 Jul 2024	3	1	4
13 Nov 2024	3	2	3
18 May 2025	3	1	2
17 Jul 2025	3	0	3

Physical Properties

Date	TAN (mg KOH/g)	Water (Hot Plate)
16 Jul 2024	0	0
16 Jul 2024	2.3	0
13 Nov 2024	1.8	0
18 May 2025	1.7	0
17 Jul 2025	1.7	0

Results and comments of this analysis are advisory only. The validity of the data may be impaired by a non-representative sample or incorrect data. © 2016-2024 ExxonMobil. ExxonMobil and Mobil are trademarks or registered trademarks of ExxonMobil Corporation or one of its subsidiaries. Other trademarks shown are property of their respective owners.

1 of 2

	Alert	
	Unit ID: 4-PHU-2	Asset ID: 50326105
	Description: Hyd pump	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25308253045 Service Level: Essential Bottle ID: a003623808 Tested Lubricant: QUAKER QUINTOLUBRIC 888-46	Asset Class: Hydraulic Manufacturer: Model: Lubricant: QUAKER QUINTOLUBRIC 888-46
Continued		
Recommendation/Comments		

ACTION REQUIRED - ELEVATED IRON LEVEL. Determine source of Iron (Fe) and take corrective action. If the iron level is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. Possible sources of iron include: a. Machinery component wear; b. Metal-to-metal contact; c. Corrosion; d. Abrasive dirt contamination. The oil may be unfit for continued use and should be closely monitored for further condition regressions. Inspect the equipment for signs of damage. Change the oil after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - EXCESSIVE IRON LEVEL. Determine source of Iron (Fe) and take corrective action. If the iron level is excessive for the first time with no history of an increasing trend, then resample immediately to confirm condition. The oil and filter are unfit for continued use. Change the filter immediately and either centrifuge or change the oil. Prolonged usage of oil with excessive iron levels can adversely affect product performance and damage the equipment. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - ELEVATED OIL VISCOSITY. Determine cause of elevated oil viscosity and take corrective action. Elevated viscosities can interfere with the cooling process of components and restrict oil flow causing oil starvation and component wear. Possible causes of elevated viscosity include: a. Contact with oil that has a higher viscosity; b. High rates of oxidation and oil degradation; c. Excessive sediment; d. Coolant contamination. A partial drain and refill with fresh oil may rejuvenate the oil condition. Change the oil immediately if the condition escalates. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - UNSATISFACTORY OIL CONDITION. Test results indicate that the condition of this oil sample is unsatisfactory. The oil may be unfit for continued use and should be closely monitored further condition regressions. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 17 Jul 2025 7:32 PM UTC - Brad Roy - In Service Oil Sample Comments: Photo: