

## Summary report

Wellbore: 15/9-F-12

Period: 2016-10-20 00:00 - 2016-10-21 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	16
Days Ahead/Behind (+/-):	5.9
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2007-03-15 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	2007-08-26

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia ():	
Pressure Test Type:	leak off test
Formation strength ():	
Dia Last Casing ():	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	3519
Depth At Last Casing mTVD:	3107.8

### Summary of activities (24 Hours)

- Cut and pulled riser
- Installed hatches
- Skidded rig to well F-11 B

### Summary of planned activities (24 Hours)

- Pull riser on well F-11 B
- Skid to F-1 C
- Pull riser on well F-1 C
- Skid to well F-7

### Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:15	0	plug abandon -- other	ok	R/D cutting machine
00:15	00:45	0	plug abandon -- other	ok	L/O upper pup and splash zone joint (Lift #2) Pulled riser (Lift #3).
00:45	01:15	0	plug abandon -- other	ok	R/U cutting machine Cut riser. Significant wave height 1 m. R/D cutting machine
01:15	01:45	0	plug abandon -- other	ok	L/O riser joint (Lift #3). Pulled riser (Lift #4), cleaned off marine growth on centralizer deck. Riser out of splash zone at 01:45
01:45	02:15	0	plug abandon -- other	ok	R/U cutting machine Cut riser R/D cutting machine
02:15	02:45	0	plug abandon -- other	ok	L/O riser joint (Lift #4). Pulled riser (Lift #5), cleaned off marine growth on centralizer deck.
02:45	03:15	0	plug abandon -- other	ok	R/U cutting machine Cut riser R/D cutting machine
03:15	03:45	0	plug abandon -- other	ok	L/O riser joint (Lift #5). Pulled riser (Lift #6), cleaned off marine growth on centralizer deck.
03:45	04:30	0	plug abandon -- other	ok	R/U cutting machine Cut riser R/D cutting machine
04:30	05:15	0	plug abandon -- other	ok	L/O riser joint (Lift #6). Pulled out with lower pup joint and stress joint (Lift #7). Installed master bushing. L/O lower pup and stress joint.
05:15	05:30	0	plug abandon -- other	ok	Cleaned and cleared drill floor for excess equipment.
05:30	07:45	0	plug abandon -- other	ok	Cleared WH decks for excess equipment.  Meanwhile: Performed skidding checks.
07:45	08:15	0	plug abandon -- other	ok	Installed hatch in moonpool  **** END OF REPORT ****